



**BOSCH**

Invented for life

## **BVMS - Release notes**

Author: Verhaeg Mario (BT-SC/PAS4-MKP)  
Date: 11-Apr-2019 16:08

<b>1</b>	<b>Document history</b>	<b>5</b>
<b>2</b>	<b>BVMS Version 9.0</b>	<b>6</b>
2.1	New functionality	6
2.2	Installation Notes	7
2.3	Versions	7
2.4	Hardware drivers	9
2.5	Patches issued	10
2.6	Resolved issues	10
2.7	Known issues	10
<b>3</b>	<b>BVMS Version 8.0</b>	<b>14</b>
3.1	Introduction	14
3.2	New functionality	14
3.3	Installation Notes	14
3.4	Firmware	14
3.5	Hardware drivers	16
3.6	Patches issued	17
3.7	Resolved issues	18
3.8	Known issues	18
<b>4</b>	<b>BVMS Version 7.5</b>	<b>20</b>
4.1	Introduction	20
4.2	New features	20
4.3	Installation Notes	20
4.4	Firmware	20
4.5	Hardware	22
4.6	Patches issued	22
4.7	Resolved issues	23
4.8	Known issues	23
<b>5</b>	<b>Bosch Video Management System Version 7.0</b>	<b>26</b>
5.1	Introduction	26
5.2	New features	26
5.3	Installation Notes	26
5.4	Firmware	26
5.5	Hardware	28
5.6	Resolved issues	28
5.7	Known issues	28
<b>6</b>	<b>Bosch Video Management System Version 6.5</b>	<b>31</b>
6.1	Introduction	31
6.2	New features	31

6.3	Installation Notes	31
6.4	Firmware	31
6.5	Hardware	33
6.6	Resolved issues	33
6.7	Known issues	34
<b>7</b>	<b>Bosch Video Management System 6.0</b>	<b>37</b>
7.1	Introduction	37
7.2	New features	37
7.3	Installation Notes	37
7.4	Firmware	38
7.5	Hardware	39
7.6	Resolved issues	39
7.7	Known issues	40
<b>8</b>	<b>Bosch Video Management System 5.5.8</b>	<b>45</b>
8.1	Introduction	45
8.2	New features in 5.5.8	45
8.3	Installation Notes	45
8.4	Firmware	45
8.5	Hardware	46
8.6	Resolved issues in version 5.5.8	47
8.7	Known issues in version 5.5.8	47
<b>9</b>	<b>Bosch Video Management System 5.5.5</b>	<b>48</b>
9.1	Introduction	48
9.2	New features in 5.5.5	48
9.3	Installation Notes	48
9.4	Firmware	48
9.5	Hardware	50
9.6	Known issues in version 5.5.5	50
9.7	Resolved issues in version 5.5.5	50
9.8	Restrictions panorama camera	50
9.9	Known issues since version 1.0	51
<b>10</b>	<b>Bosch Video Management System 5.5</b>	<b>61</b>
10.1	New features in version 5.5	61
<b>11</b>	<b>Bosch Video Management System 5.0.5</b>	<b>62</b>
11.1	Feature enhancements in version 5.0.5	62
<b>12</b>	<b>Bosch Video Management System 5.0</b>	<b>63</b>
12.1	New features in version 5.0	63
<b>13</b>	<b>Bosch Video Management System 4.5.9</b>	<b>65</b>
13.1	New features in version 4.5.9	65

<b>14 Bosch Video Management System Version 4.5.8</b>	<b>66</b>
14.1 New features in version 4.5.8	66
<b>15 Bosch Video Management System Version 4.5.5</b>	<b>67</b>
15.1 New features in version 4.5.5	67
<b>16 Bosch Video Management System Version 4.5.1</b>	<b>68</b>
16.1 Feature enhancements in version 4.5.1	68
<b>17 Bosch Video Management System Version 4.5</b>	<b>69</b>
17.1 New features in version 4.5	69
<b>18 Bosch Video Management System Version 4.0</b>	<b>70</b>
18.1 New features in version 4.0	70
<b>19 Bosch Video Management System Version 3.0.1</b>	<b>71</b>
19.1 New features in version 3.0.1	71
<b>20 Bosch Video Management System Version 3.0</b>	<b>72</b>
20.1 New features in version 3.0	72

# 1 Document history

This document is valid for all BVMS versions. Only the release notes of the latest BVMS version are fully updated and contain updates for earlier versions as well.

Date	Version	Changes
2018-11-16	BVMS 9.0	Added VIP-XD to list of supported devices. Added Video Streaming Gateway 6.45.0005.
2018-11-22	BVMS 9.0	Added bug 179879, 218284, 215086, 217354, 205190, 216797, 211909
2018-12-04	BVMS 9.0, 8.0, 7.5	Added section on published patches.
2018-12-04	BVMS 7.5	Added bug 191832, 205190.
2018-12-12	BVMS 9.0, 8.0, 7.5	Updated "Firmware" section with new test results.
2018-12-18	BVMS 9.0	Added bug 219618 and workaround.
2018-12-28	BVMS 7.5	Added fix 204822.
2019-01-02	BVMS 9.0	Added bug 219769.
2019-01-18	BVMS 9.0	Added fix 207457, 218718, 222090.
2019-03-29	BVMS 9.0	Added functionality 172164.
2019-04-03	BVMS 9.0	Added fixes 223779, 221394.
2019-04-03	BVMS 9.0, 8.0, 7.5, 7.0	Updated "Firmware" section with new test results.
2019-04-03	BVMS 9.0, 8.0, 7.5	Added CVE-2019-6957 / CVE-2019-6958 (219829).
2019-04-11	BVMS 8.0	Added fixes 206026.

## 2 BVMS Version 9.0

This document is distributed within the installation package, but is updated from time to time. The latest version of the Release Notes is always available on the [Bosch Security Systems Product Catalog](#). Version 9.0 introduces new features and resolved issues to BVMS.

### 2.1 New functionality

ID	Description
172164	Configure 800 iSCSI session and 1000Mbit/s on the "other" iSCSI device
160421	Safe delivery of software
163204	Enable B-frames in live and playback
165742	Add an unmanaged network device using hostname
187167	Test DL380 G10
165743	Add a DVR to the system with a deviating port
184368	Persistent alarms when management server is (gracefully) restarted
184396	BVMS operator client is able to replay exports from the VRM eXport Wizard
184363	Implement a state event when an export is running
184369	Configure a maximum retention time for the logbook
184364	Device icon blinks while an alarm is active
184376	Alarms cannot be cleared when originating state has not changed
184377	Prevent duplicated alarms from the same device and event
174321	Microsoft SQL Server 2017 Express integrated
134518	BVMS Dark color theme
172229	Enable GOPs up to 255 in live and playback
170202	Manual access control authorization [ <b>hidden</b> ]
191808	BVMS Plus licensing scheme
163693	Replace a camera without losing recording
191482	Move bonus documentation files from installation to <a href="https://community.boschsecurity.com">https://community.boschsecurity.com</a>
184373	Extended user and password management
184374	Several SDK extensions
184375	Enhancements and extensions of configuration reports

ID	Description
184367	Camera maintenance (deactivation) mode
184366	Restricted access to VRM monitor
190920	Update existing recording profiles to match recommended camera settings
184371	Permissioned configuration client
197341	Move Analog Monitor Group (AMG) control to the image-pane
182352	Optimize ePTZ handling for 180 degree panoramic cameras Adjust default zoom level for all panoramic cameras
180441	Limit the number of image panes per user group
155461	Allow non-BVMS clients (Video Security Apps) to access the BVMS user authentication service
160582	Configure CHAP passwords for cameras, enabling ANR and local replay.
191896	Barco agent 0.9.5.0 (tested with encoder passwords)
191194	Searching for access control events [ <b>hidden</b> ]

## 2.2 Installation Notes

For system design specifications the BVMS datasheet, configuration manual, pre-sales guide and quick installation guide should be used. These can be found on <http://www.boschsecurity.com> and <http://knowledge.boschsecurity.com>. The datasheet is subject to change. Translated versions are not published instantly; the English version is always up-to-date.

## 2.3 Versions

The table below lists the firmware versions which are used in the BVMS system test.

### Device Compatibility

Up until some years ago, new released cameras, encoders, domes and decoders that are introduced into market after a BVMS release could not be connected to an existing BVMS version because these cameras were not known to the BVMS. In the BVMS 4.5.1, a new concept was introduced. This concept treats Bosch video encoders and decoders as generic devices, and automatically recognizes specific device functionality (for example the number of streams, relays and inputs). Based on this information the, at that time, unknown device is added to the system and can be used by the operator. This document, which can be found in the Bosch Building Technologies community, provides a detailed description of this functionality: [BVMS - Device compatibility](#).

Component	Version
Bosch Video Stitcher	1.6.0.63
VideoSDK	6.31.0067
Firmware MPEG-4	4.15.0002

Component	Version
Firmware CPP3	5.74.0010
Firmware CPP4	6.50.0128 / 6.51.0026 / 6.51.0028 / 6.60.0065 / 6.61.0025
Firmware CPP5	6.30.0059
Firmware CPP6	6.50.0128 / 6.51.0026 / 6.51.0028 / 6.60.0065 / 6.61.0025
Firmware CPP7	6.50.0128 / 6.51.0026 / 6.51.0028 / 6.60.0065 / 6.61.0025
Firmware CPP7.3	6.50.0128 / 6.51.0026 / 6.51.0028 / 6.60.0065 / 6.61.0025
Firmware CPP-ENC	5.53.0004 (for VIP X1600 XFM4)
Firmware CPP-ENC	5.97.0005 / 5.97.0007 (for VJT XF E family, VIDEOJET decoder 3000)
Firmware X1/X2	2.53.0005
VIP XD HD	1.8
VIP XD	4.10.056
VJD 7000	54.8.2
VJD 8000	9.10.0029
VRM	3.81.0032 (32-bit) / 3.81.0038 (32-bit) / 3.81.0048 (32-bit)
VSG	6.44.0022 / 6.45.0005 / 6.45.0006 / 6.45.0008
<b>iOS</b>	9.0.2 / 9.3.5 / 10.3.1 / 11.4
Web Client	11.165
BIS	4.4, 4.5, 4.6
DiBos	8.7
BRS	8.10/8.11
Allegiant MCS	2.94 / 2.95
Intuikey Keyboard	1.96



Component	Version
DVR FW Version	2.1.3 (DVR400 / 600) 3.61 (DIVAR 700) 2.5.0 (Divar AN 3000/5000) 1.4.0 (Divar Network/Hybrid)
SQL Server	2017
Operating systems Operator Client, Configuration Client.	Windows 10 Professional (64-bit) Spring Creators update (1803) Windows 10 Professional (64-bit) Fall Creators update (1709) Windows 10 Enterprise (64-bit) LTSB 2016 (1607)
Operating systems Management Server, Mobile Video Service, Video Recording Manager	Windows (Storage) Server 2012 R2 (64-bit) Windows (Storage) Server 2016 (64-bit) Windows 10 Professional (64-bit) Spring Creators update (1803) Windows 10 Professional (64-bit) Fall Creators update (1709) Windows 10 Enterprise (64-bit) LTSB 2016 (1607)
Cameo SDK	1.3.0.0
BVMS SDK	1.9.0.0
RCPP	4.61.0028

## 2.4 Hardware drivers

Component	Version
NVIDIA Quadro	Quadro Pro Driver for Microsoft Windows 10 (64-Bit) 385.69 (2017-09-21)
AMD	FirePro Unified Graphics Driver for Windows 10 (64-bit) 17.Q3 (2017-27-07)
Intel	Intel Graphics Driver for Windows 10 (64bit) - 4600 GPU - 15.40.38.4963 (5. April 2018)
Intel	Intel Graphics Driver for Windows 10 (64bit) - 530 GPU - 15.46.05.4771 (30. August 2017)

### Hardware requirements

Bosch strongly urges customers to use the driver versions mentioned above. This ensures that the software can perform its task reliably and the specified performance.

## 2.5 Patches issued

ID	Description	Fixed in	BVMS	BVMS Viewer
223779	<b>FIXED:</b> An issue caused in some cases that recording parameters are not written correctly to the devices.	10.0	<a href="#">Download</a>	<a href="#">Download</a>
221394 / 221454	<b>FIXED:</b> Enhancing the change password mechanism to improve the behaviour in cases dual authorizations are used.	10.0	<a href="#">Download</a>	<a href="#">Download</a>
221373	<b>FIXED:</b> MOV export issues (black video, seeking)	10.0	<a href="#">Download</a>	<a href="#">Download</a>
208909	<b>FIXED:</b> Enabled access control integration.	10.0	<a href="#">Download</a>	n/a
219829	<b>FIXED:</b> [CVE-2019-6957 / CVE-2019-6958] Buffer overflow and improper access control	10.0	<a href="#">Download</a>	<a href="#">Download</a>
218718	<b>FIXED:</b> Delayed actions which require user authentication	10.0	<a href="#">Download</a>	<a href="#">Download</a>
207457	<b>FIXED:</b> Inconsistent display of red dot recording state	10.0	<a href="#">Download</a>	<a href="#">Download</a>
216818	<b>FIXED:</b> Configuration client crash when malicious input was entered in the address book (DDOS)	10.0	<a href="#">Download</a>	<a href="#">Download</a>
212907	<b>FIXED:</b> Missing context menu on AMG control (clear/disconnect, toggle quad mode, set volume).	10.0	<a href="#">Download</a>	<a href="#">Download</a>
209977	<b>FIXED:</b> GPU decoding is not functioning properly with Nvidia Quadro P600.	10.0	<a href="#">Download</a>	<a href="#">Download</a>

## 2.6 Resolved issues

ID	Description
183720	<b>FIXED:</b> improved GPU/CPU balancing for 60fps cameras.
189400	<b>FIXED:</b> removed memory indicator.
182561	<b>FIXED:</b> silent login connection parameter.
117194	<b>FIXED:</b> edge-dewarping with panoramic camera.

## 2.7 Known issues

### Known issues

Known issues are inherited by previous versions. If an issue is fixed, it will appear in the list of resolved issues. The issue IDs can be used to relate an issue to a resolution.

ID	Subject	Description
222090	Language	Once a BVMS language is set, the configuration is initiated and it cannot be changed without reconfiguring the entire system.
219769	Access Control	When multiple access management systems are configured, events from only one system will be processed.
219618	SNMP	Due to a change in Windows 10 "October 2018 update" (1809), the BVMS installer is not able to install the required SNMP components. This needs to be manually installed ("Settings" app, "Apps & Features", "Manage optional features", "Install SNMP").
211909	Alarms	Compound events should not be nested: cyclic references to compound events could prevent the management server from processing other events.
216797	MVS	When an MVS is configured in the system (by default when using the Configuration Wizard on DIVAR IP appliances), but not installed, the software transcoder does not work.
208908	PTZ	Cannot move to the same preposition after manually controlling a PTZ camera.
214843	Configuration	BISProxy: app.config file contains user credentials of a BVMS user in plain text.
218284	Configuration	User data (including favourites) cannot be moved (exported/imported) from one server to another.
179879	Decoder	Decoders are not able to connect to cameras with an empty user password (even though the destination password is empty). Ensure the destination password on the decoders is matching with the user passwords on the cameras and this is not blank.
208326	Languages	The "OK" and "Cancel" buttons of the configuration client's settings dialogue are not displayed when it is running on an Operating System set with the Arabic language. The "ESC" button on the keyboard can be used to cancel, the "ENTER" button on the keyboard can be used to OK.
208193	Maps	In rare occasions the hotspots located on a map need to be re-aligned manually.
208286	DIP	BVMS 9.0 cannot be installed on first generation (DIP-70xx-xHD and DIP-30xx-xHD) DIVAR IP devices due to the outdated operating system.
207248	Streaming	The MVS (Mobile Video Service) cannot process IBBP and IBP GOP structures. Additionally it is limited to an I-frame distance of 30. When using the MVS in a BVMS system, the image optimized profiles should be used.
208062	Storage	When the recordings of an old camera are attached to a new camera, a BVMS configuration rollback to a point in time before the attachment, will result in the <u>loss of all related recordings</u> . Please wait with the rollback until the recordings of the old camera are overwritten (retention time) or restore the configuration settings manually.
208087	Storage	When the recordings of an old camera are attached to a new camera, the recordings of the old camera are not available through encoder-replay.
207780	GPU	When using the recommended Nvidia Quadro Pro Driver (385.69) on Windows Server 2012 R2 systems, h.265 streams might be distorted.

ID	Subject	Description
206756	GPU	Intel Graphics Driver for Windows 10 24.20.100.6136 cannot be used for GPU decoding. Software decoding will be used.
207814	Streaming	Reverse playback does not work when using transcoding.
207207	SSH	The connection between the operator client and the management server might be lost when using SSH and the (remote) connection is utilized over 90%.
204379	Storage	When importing the configuration from a VRM, which uses an E-Series 2800 dual controller device that is distributed across different pools, the storage device needs to be removed and re-added to your configuration in order to get the correct LUNs assigned to the pools.
203933	User management	When changing the password of an enterprise account, and the activation is activated with the "forced restart" option enabled, the connected operator clients do not restart. The operator clients need to be manually restarted.
205959	ANR	ANR replay is not working when the "access protection enforcement" and "password policy enforcement" options in the camera are enabled.
204968	GPU	A memory leak is observed when using not-recommended Nvidia driver versions, which could result in decreased system performance. Please use the recommended Nvidia drivers, as mentioned in the section above.
191527	General	<a href="#">Microsoft Support - Service does not start</a> : BVMS set-up automatically sets <code>HKEY_LOCAL_MACHINE\SYSTEM\CurrentControlSet\Control\ServicesPipeTimeout</code> to <code>60000</code> in order to ensure the BVMS services are started correctly.
182727	ONVIF	When using a multi-sensor ONVIF camera, motion detection events will be raised as a device alarm: sensor specific motion alarms cannot be processed.
205170 205166	Performance	Removing up to 9999 devices and/or items from the configuration can take up to 2 minutes.
203910	SDK	The <code>DisplayCameraInInstantPlayback</code> SDK function cannot be used in the BVMS Enterprise Client SDK.
200816	SDK	The <code>RemoteClientApi</code> SDK functions in the BVMS script engine cannot be used from the BVMS Server. An external application needs to be used to control the client using the <code>RemoteClientApi</code> .
189629	Audio	The G726 audio codec cannot be used combined with ONVIF cameras.
195810	Storage	Exports done by using the VRM eXport Wizard do not contain time-zone information. The time will be mapped to the UTC time-zone.
200514	Streaming	When using a very long GOP (up to 255) combined with a low frame-rate (1fps) the (time) distance between the i-frames is too large and playback cannot be displayed. Bosch recommends reducing the GOP length to 30 in this scenario.

ID	Subject	Description
172229	Streaming	When using a very long GOP (up to 255) the operator client needs to load the entire GOP in order to display the right image. This will cause an additional load on the network and storage, which makes long GOPs less suitable for low-bandwidth environments in which the operator wants to quickly browse through video. Bosch recommends reducing the GOP length to 30 in this scenario.
195698	Decoder	The Analogue Monitor Group (AMG) control has been moved from a fixed area of the operator client to an image-pane based control. When a BVMS system is upgraded, and using AMG, the control should be added to the logical tree to ensure operators have access to the AMG functionality after the upgrade.
192510	General	Due to the upgrade to Microsoft SQL Server 2017 BVMS 9.0 cannot be installed on Microsoft Windows 7 and Windows Server 2008 R2. Additionally the BVMS set-up size has increased.
192510	General	When upgrading an existing BVMS version to BVMS 9.0, the set-up needs to be manually restarted after the installation of Microsoft SQL Server 2017 has completed and the server has been restarted.
196172	Decoder	Dome-presets in a sequence do not work when the sequence is controlled from the digital monitor wall. This only works when the sequence is controlled from the analog monitor group.
198610	Streaming	GOPs larger than 255 will not be decoded.
189289	Streaming	B-frames will only be enabled on encoders which explicitly support this and are running FW 6.40 or newer.
191197	Storage	All LUNs that are scanned on an iSCSI target are added to the configuration.
186267 / 189329	Security	HTTPS encryption between DVRs and BVMS system components is only applicable for "control" traffic, not for video streams.
189681	Connectivity	When connecting to a DIVAR Hybrid and Network in a routed/NAT setup, using a different port than 443 or 80, video (live and recording) will not be shown.
199271	Export	When exporting using MOV, the MOV playlist might not play. The individual files will play.
196239	Streaming	When using a very long GOP (up to 255) and using I-frame only recording, the video will not show smoothly or completely disappear.
190090	Alarms	The file in which alarms are stored (persistent alarms) is removed when upgrading the system.

## 3 BVMS Version 8.0

### 3.1 Introduction

The latest version of the Release Notes is always available on the [Bosch Security Systems Product Catalog](#). Version 8.0 introduces new features and resolved issues to the BVMS.

### 3.2 New functionality

ID	Description
165770	Move to 64-bit software architecture
146474	Favorites can be used in combination with unmanaged sites
172375	SSH connectivity can be used in combination with unmanaged sites
173425	The "Admin" username can be changed
158123	SDK: remove protection from recordings
169488	Support bi-directional audio for MIC 7000 combined with Videojet Connect 7000
144613	Improve operator client performance by Nvidia GPU decoding
144682	DSA E-series 2800 single controller preparations
134122	Live, playback, asf-, mov-, and native export of H.265 devices
160935	Implementation of MIC 9000 specific user interface options
156279	Microsoft Windows Server 2016 is added to the system test.
157936	Fault-tolerance based on Stratus Everrun
160516	Show IVA rule configuration in Operator Client (overlay)
174552	Barco agent 0.9.4.0 tested

### 3.3 Installation Notes

For system design specifications refer to the BVMS datasheet, Configuration Manual, pre-sales guide and Quick Installation Guide on <http://www.boschsecurity.com>. The datasheet is subject to change. Translated versions are not published instantly, for the latest version refer to the English version.

The installation manual and additional documentation of Bosch DSA E-Series iSCSI disk arrays can be found in Bosch on-line product catalogue on <http://www.boschsecurity.com>.

### 3.4 Firmware

The table below lists the firmware versions which are used in the BVMS system test.

### Device Compatibility

Up until some years ago, new released cameras, encoders, domes and decoders that are introduced into market after a BVMS release could not be connected to an existing BVMS version because these cameras were not known to the BVMS. In the BVMS 4.5.1, a new concept was introduced. This concept treats Bosch video encoders and decoders as generic devices, and automatically recognizes specific device functionality (for example the number of streams, relays and inputs). Based on this information the, at that time, unknown device is added to the system and can be used by the operator. This document, which can be found in the Bosch Building Technologies community, provides a detailed description of this functionality: [BVMS - Device compatibility](#).

Component	Version
Bosch Video Stitcher	1.6.0.63
VideoSDK	6.12.0078 / 6.15.0103
Firmware MPEG-4	4.15.0002
Firmware CPP3	5.74.0004
Firmware CPP4	6.41.0037 / 6.42.0021 / 6.43.0027 / 6.51.0026 / 6.44.0027 / 6.51.0028
Firmware CPP5	6.30.0047 / 6.30.0059
Firmware CPP6	6.41.0037 / 6.42.0021 / 6.43.0027 / 6.51.0026 / 6.44.0027 / 6.51.0028
Firmware CPP7	6.41.0037 / 6.42.0021 / 6.43.0027 / 6.51.0026 / 6.44.0027 / 6.51.0028
Firmware CPP7.3	6.41.0037 / 6.42.0021 / 6.43.0027 / 6.51.0026 / 6.44.0027 / 6.51.0028
Firmware CPP-ENC	5.53.0004 (for VIP X1600 XFM4)
Firmware CPP-ENC	5.97.0005 (for VJT XF E family, VIDEOJET decoder 3000)
Firmware X1/X2	2.53.0005
VIP XD HD	1.8
VJD 7000	54.8.2
VJD 8000	9.00.0134
VRM	3.70.0056 / 3.71.0022 / 3.71.0029 / 3.71.0031
VSG	6.42.0010 / 6.43.0017

Component	Version
iOS	9.0.2 / 9.3.5 / 10.3.1
Web Client	11.0.96
BIS	4.3, 4.4, 4.5
DiBos	8.7
BRS	8.10/8.11
Allegiant MCS	2.94 / 2.95
Intuikey Keyboard	1.96
DVR FW Version	2.1.3 (DVR400 / 600) 3.61 (DIVAR 700) 2.5.0 (Divar AN 3000/5000) 1.2.1 (Divar Network/Hybrid)
SQL Server	2014
Operating systems Operator Client	Windows 8.1 64-bit; Windows 10 64-bit creators update (1703)
Operating systems Config Client	Windows 8.1 64-bit; Windows 10 64-bit; Windows Server 2012 R2 64-bit; Windows Server 2016 64-bit.
Operating systems Management Server, Mobile Video Service	Windows Server 2008 R2 SP1 64-bit (DIVAR IP only); Windows Server 2012 R2 64-bit; Windows Server 2016 64-bit.
Cameo SDK	1.3.0.0
BVMS SDK	1.9.0.0
RCPP	4.53.0.35

## 3.5 Hardware drivers

Component	Version
NVIDIA Quadro	Quadro Pro Driver for Microsoft Windows 7/8.1 (64-Bit) 385.08 (28.June 2017) Quadro Pro Driver for Microsoft Windows 10 (64-Bit) 385.69 (21.September 2017)



Component	Version
AMD	FirePro Unified Graphics Driver for Windows 8.1/10 (64-bit) 17.Q3 (27.July 2017)

#### Hardware requirements

Bosch strongly urges customers to use the driver versions mentioned above. This ensures that the software can perform its task reliably.

## 3.6 Patches issued

ID	Description	Fixed in	BVMS	BVMS Viewer
206026 / 207547	<b>FIXED:</b> inconsistent state display of red dot recording state overlay.	10.0	<a href="#">Download</a>	<a href="#">Download</a>
219829	<b>FIXED:</b> [CVE-2019-6957 / CVE-2019-6958] Buffer overflow and improper access control.	10.0	<a href="#">Download</a>	<a href="#">Download</a>
216927 / 190582	<b>FIXED:</b> inappropriate handling of inputs in the timeline date/time edit box; out-of-sync replay for DVR cameras on replay position change with the UXF keyboard.	9.0	<a href="#">Download</a>	<a href="#">Download</a>
202562 / 205267 / 198002 / 195261	<b>FIXED:</b> Operator Client showed black images while replaying exports; ImageDecoder log directories with a constantly growing number of log files; video display issues with VIP 10 devices; missing IVAe overlays in CameoSDK applications.	9.0	<a href="#">Download</a>	<a href="#">Download</a>
205263 / 203669 / 199314	<b>FIXED:</b> Invalid display of maps in some cases, Configuration Client to crash on conversion of specific maps.	9.0	<a href="#">Download</a>	<a href="#">Download</a>
198854	<b>FIXED:</b> Missing favorites in offline situations.	9.0	<a href="#">Download</a>	<a href="#">Download</a>
208696	<b>FIXED:</b> The Operator Client crashed on video stream loss under certain circumstances.	9.0	<a href="#">Download</a>	<a href="#">Download</a>
216818	<b>FIXED:</b> Configuration client crash when malicious input was entered in the address book (DDOS)	10.0	<a href="#">Download</a>	<a href="#">Download</a>
216927	<b>FIXED:</b> Date selection for timeline is not valid if day or month is entered as single digit	9.0	<a href="#">Download</a>	<a href="#">Download</a>
185070	<b>FIXED:</b> Implemented multipathing for DSA E-series 2800	9.0	<a href="#">Download</a>	<a href="#">Download</a>
190582	<b>FIXED:</b> Out-of-sync replay for DVR cameras on replay position change with the UXF keyboard.	9.0	<a href="#">Download</a>	<a href="#">Download</a>
189002, 195261	<b>FIXED:</b> the Operator Client showed black images while replaying exports.	9.0	<a href="#">Download</a>	<a href="#">Download</a>

ID	Description	Fixed in	BVMS	BVMS Viewer
195380	<b>FIXED:</b> alarm recording stopped in some cases when triggering a configuration change.	9.0	<a href="#">Download</a>	<a href="#">Download</a>

## 3.7 Resolved issues

ID	Description
161444	<b>FIXED:</b> For some profiles, the default value for target bit rate is higher than the value of the maximum bit rate.
30130	<b>FIXED:</b> VRM System camera/encoder scan renames cameras
170208	<b>FIXED:</b> Instead of "freezing" the (live) video when the network experiences packet loss, the video will now be decoded on best-effort. As a result, network issues are shown to the operator as artifacts.

## 3.8 Known issues

ID	Description
215086	In some cases Bosch H.265 cameras cannot be added to the system configuration using the "Scan encoders" dialogue. Workaround: add the cameras manually based on their IP address.
217354	Configuration Client might crash when the scriptlet ID of a script is changed manually in the script editor.
205190	OPC xml file (exported from the BVMS Configuration Client) does not contain DVR devices.
VRM-2983	<a href="#">Possible Communication Issue between BVMS 8.0 and VRM 3.70 or 3.71</a>
183720	The performance estimations of some GPUs are not fully correct, which could lead to a performance decrease compared to CPU decoding. GPU decoding can be disabled as a work-around. The exact impact is listed in the BVMS project checklist.
183162	In some situations connecting to a DIVAR Hybrid or Network may take longer than 20 seconds.
172618	The Netapp FAS 2040 cannot be configured from the BVMS Configuration Client.
183179/183372	In some situations MPEG4 connected VSG cameras cannot be replayed anymore.
184192	The SSH tunneling protocol cannot be used to connect the BVMS Configuration Client to the BVMS Management server.
184327	When the language of the operating system is set to Turkish, the Bosch Video Stitcher cannot be licensed. Please set the operating system language to English.
182788	When firmware 6.40 or 6.41 is used on the camera, video authentication will not work. Keep firmware 6.32 if this functionality is used.
182804	The input states of a Bosch DIVAR 400 and DIVAR 600 are not monitored.
81663	ANR enabled cameras, or local storage cameras, are not able to replay video if any live or user password is set.

ID	Description
157312	Forensic search is not possible on video footage exported from BVMS.
179879	When the "access protection enforcement" of a Bosch encoder (running firmware 6.40 or newer) is enabled, the video cannot be displayed on decoders. In order to work-around the issue a "user" password needs to be set on the encoder, and the "destination" password needs to be set on the decoder. The user and destination password needs to match.
171880	When an encoder is configured with invalid (definition can be found in the configuration manual) password characters a pre-set will not be triggered.
n/a	The MVS is not able to transcode H.265 video.
170401	Due to the migration to the 64-bit software architecture 32-bit CameoSDK applications cannot connect to the BVMS 8.0 management server.
169982	The OIDs of SNMP traps might be shifted after upgrading to BVMS 8.0. The alarms configured in the receiving system need to be adjusted to the new OIDs.
171856	After locking the pc, and logging in again, the Operator Client can crash when using non-tested Nvidia drivers. This problems has been confirmed by Nvidia and Bosch strongly recommends using the tested Nvidia driver version mentioned earlier in this document.
172049	The motion+ search algorithm is only available for analogue cameras connected to a DIVAR Network or Hybrid.
165214	Hotspots might be flickering when moving the map.
164871	DIVAR AN, Network and Hybrid devices show the wrong interval in the time-line for protected and restricted video.
156070	After changing the IP address of a camera from the BVMS Config Client the VRM service needs to be stopped, the VRM config.xml needs to be removed, and the VRM service needs to be restarted.
165472 / 173637	Authentication problems are known when using Axis cameras combined with BVMS. Axis has released new firmware to mitigate this problem. The recommended firmware can be found on <a href="http://ipp.boschsecurity.com/bvms">http://ipp.boschsecurity.com/bvms</a>
156105 / 167598	BVMS is not able to use the transcoding resources offered by the Videojet XTC transcoder.
167294	In some situations decoding problems might arise when trying to decode a Hirschmann encoder.
173162	In rare situations the Operator Client can crash when a camera is opened which is authenticated using invalid password-characters.

## 4 BVMS Version 7.5

### 4.1 Introduction

The latest version of the Release Notes is always available on the Bosch Product Catalog ([www.boschsecurity.com](http://www.boschsecurity.com)). Version 7.5 introduces new features and resolved issues to the BVMS.

### 4.2 New features

ID	Description
153834	DIVAR Network / Hybrid supported
69032	Map viewer improved
157938	Forensic Search license not needed any more
138588	Accelerated playback speed (I-frame only playback)
155351	Camera PTZ control via BIS
155352	Start and stop sequences via BIS
155353	Added "visibility" state to camera state
108262	The Operator Client can communicate with the full system using a single network port.
147027	Windows 10 and Windows Server 2016 supported for BVMS Management Server

### 4.3 Installation Notes

For system design specifications refer to the BVMS datasheet, Configuration Manual, pre-sales guide and Quick Installation Guide on <http://www.boschsecurity.com>. The datasheet is subject to change. Translated versions are not published instantly, for the latest version refer to the English version.

The installation manual and additional documentation of Bosch DSA E-Series iSCSI disk arrays can be found in Bosch on-line product catalogue on <http://www.boschsecurity.com>.

### 4.4 Firmware

#### Device Compatibility

Up until some years ago, new released cameras, encoders, domes and decoders that are introduced into market after a BVMS release could not be connected to an existing BVMS version because these cameras were not known to the BVMS. In the BVMS 4.5.1, a new concept was introduced. This concept treats Bosch video encoders and decoders as generic devices, and automatically recognizes specific device functionality (for example the number of streams, relays and inputs). Based on this information the, at that time, unknown device is added to the system and can be used by the operator. This document, which can be found in the Bosch Building Technologies community, provides a detailed description of this functionality: [BVMS - Device compatibility](#).

Component	Version
VideoSDK	6.0.5.288
Firmware MPEG-4	4.15.0002
Firmware CPP3	5.74.0004
Firmware CPP4	6.32.0111 / 6.32.0111 / 6.40.0232 / 6.44.0027
Firmware CPP5	6.30.0047 / 6.31.0003 / 6.30.0059
Firmware CPP6	6.32.0111 / 6.32.0111 / 6.40.0232 / 6.44.0027
Firmware CPP7	6.32.0111 / 6.32.0111 / 6.40.0232 / 6.44.0027
Firmware CPP-ENC	5.53.0004 / 5.54.0004 (for VIP X1600 XFM4)
Firmware CPP-ENC	5.97.0005 / 5.97.0007 (for VJT XF E family, VIDEOJET decoder 3000)
Firmware X1/X2	2.53.0005
VIP XD HD	1.8
VDJ 7000	54.8.2
VDJ 8000	8.21.0028
VRM	3.60.0053 / 3.70.0056 / 3.70.0062 / 3.71.0031
VSG	6.30.0055
iOS	7.1.1 / 8.3 / 9.0.2 / 9.3.5 / 10.0.1
Web Client	11.0.96
BIS	4.2 / 4.3
Bintelan Analytics Platform	5.7.5955.25388
DiBos	8.7
BRS	8.10/8.11
Allegiant MCS	2.94

Component	Version
Intuikey Keyboard	1.96
VMWare	5.1.0
DVR	2.3.2 (DVR400 / 600) 3.60 (DIVAR 700) 1.1.2 (Divar Network/Hybrid)
Operating systems Operator Client	Windows 7 64-bit, Windows 8.1 64-bit; Windows 10 64-bit anniversary update
Operating systems Config Client	Windows 7 64-bit, Windows 8.1 64-bit; Windows 10 64-bit; Windows Server 2008 R2 SP1 64-bit; Windows Server 2012 R2 64-bit; Windows Server 2016
Operating systems Management Server, Mobile Video Service	Windows Server 2008 R2 SP1 64-bit; Windows Server 2012 R2 64-bit; Windows Server 2016
CameoSDK	1.3.0.0
BVMS SDK	1.9.0.0

## 4.5 Hardware

### Hardware requirements

For the HW-requirements of other components like VRM, VSG, Allegiant MCS – Please refer to the documentation of these components

Component	Version
NVIDIA Quadro	Driver for Windows 7 and Windows 8.1 (64-bit): 381.65 Driver for Windows 10 (64-bit): 377.11
AMD	Driver for Windows 8.1 (64-bit) 17.Q1.1 Driver for Windows 10 (64-bit) 17.Q1.1

## 4.6 Patches issued

ID	Description	Fixed in	BVMS	BVMS Viewer
219829	<b>FIXED:</b> [CVE-2019-6957 / CVE-2019-6958] Buffer overflow and improper access control	10.0	<a href="#">Download</a>	<a href="#">Download</a>

ID	Description	Fixed in	BVMS	BVMS Viewer
204822	<b>FIXED:</b> Memory leak on frequent CameoSDK connects/disconnects and an operator client crash in some cases when opening cameras of a Videojet Multi 4000.	9.0	<a href="#">Download</a>	<a href="#">Download</a>
216818	<b>FIXED:</b> Configuration client crash when malicious input was entered in the address book (DDOS)	10.0	<a href="#">Download</a>	<a href="#">Download</a>
207457	<b>FIXED:</b> Inconsistent state display of red dot recording in Operator client.	10.0	<a href="#">Download</a>	<a href="#">Download</a>
190762	<b>FIXED:</b> Problems with retrieving ONVIF topics and subscribing ONVIF events.	9.0	<a href="#">Download</a>	<a href="#">Download</a>
176748	<b>FIXED:</b> Problems with topics and events of SightLogix NS-90 thermal camera.	8.0	<a href="#">Download</a>	<a href="#">Download</a>
191701	<b>FIXED:</b> Toggling relays with the IntuiKey keyboard does not work in some cases.	9.0	<a href="#">Download</a>	<a href="#">Download</a>
197578	<b>FIXED:</b> Configuration Client logins failed for systems with special IntuiKey keyboard login constellations.	9.0	<a href="#">Download</a>	<a href="#">Download</a>
194599	<b>FIXED:</b> Specific GSM modem models failed to send SMS messages.	9.0	<a href="#">Download</a>	<a href="#">Download</a>
173617	<b>FIXED:</b> Dome preview failures on Configuration Client..	8.0	<a href="#">Download</a>	<a href="#">Download</a>

## 4.7 Resolved issues

ID	Description
161444	<b>FIXED:</b> For some profiles, the default value for target bit rate is higher than the value of the maximum bit rate.
30130	<b>FIXED:</b> VRM System camera/encoder scan renames cameras
147278	<b>FIXED:</b> When using the Bosch VMS CameoSDK, frequent connect/disconnect can cause a memory leak. It is recommended to use a permanent connection when using the CameoSDK.

## 4.8 Known issues

ID	Topic	Description
191832	MVS	Mobile Video App cannot use DDNS URL for login.
n.a.	SSH	The SSH service cannot be used in an BVMS Enterprise Management environment.
150009	Decoder	Videojet decoder 7000 / 8000 do not support audio in BVMS
n.a	Decoder	Videojet connect 7000 does not support audio out

ID	Topic	Description
165163	VRM	Changing name of a Video Recording Manager in BVMS does NOT change the "VRM Server Name" on the cmlib-page of the VRM
n.a.	VRM	When adding a VRM device to a BVMS Configuration, BVMS enables the RCP+ protocol
n.a.	VRM	When importing a VRM configuration, ONVIF or Bosch PTZ cameras configured under a VSG are not detected as PTZ cameras. PTZ configuration has to be done manually on camera and recording page
161813	BIS	When the BVMS SDK or OPC server is used for controlling Pan-Tilt-Zoom cameras, the zoom speed may differ between cameras.
152699	Streamlining	Automatic Stream Selection cannot be used when the Operator Client is connected to an unmanaged site, even though this is offered by the user interface.
155788	ANR	Audio is not working for ANR playback.
156342	Configuration	On all-in-one systems, configuring an iSCSI target requires the BVMS Config Client to have administrative rights.
157929	VSG	It is not possible to access an ONVIF device which is not configured as part of a Video Streaming Gateway in a remote access scenario.
154912	Maps	The total amount of hotspots open in one or multiple maps is 4.000.
142140	ANR	The video authenticity check is not working for cameras which are using ANR recording.
155514	Configuration	When using Windows 10, a device scan searching for the DIVAR AN 3000/5000 brings no result. The device(s) need to be added manually or the scan needs to be executed on another operating system.
160979	PTZ	Pan-Tilt-Zoom dome cameras that are connected via the Bosch Recording Station cannot be controlled using the BVMS SDK or BIS server.
155706	Configuration	Changing the IP address of a password protected device in a different sub net is not working.
160930	MVS	When storing the Mobile Video Service certificate from Internet Explorer it should be stored in the "Other People / Certificates" store.
155532	MVS	Disabling the HTTP protocol (using HTTPS only) will prevent the Management Server to communicate with the Mobile Video Service.
39436	Recording	If a "user" password is set to a camera used for local recording, the Operator Client is not able to access the recording.
162254	Configuration	The installation of the .NET framework 4.6 is possible by following the MS instructions to install KB2919355 first.
145024 145026	External	The Barco Transform A series RCP+ agent does not work anymore. The Barco Transform N series will work with the corresponding RCP+ agent (0.9.0.7).



ID	Topic	Description
149922	Recording	When exporting recorded footage with changing FPS rates the display of frame rate may be wrong
155405	Configuration	The initial configuration of an Infortrend is not possible anymore.
135338	ONVIF	The ONVIF event subscription filtering does not work for all camera manufacturers.
164622	ONVIF	For the integration of Axis Cameras, the camera FW needs to be as specified in the list of BVMS 7.5 compatible 3rd party cameras. Newer Axis camera firmware versions such as 5.90 and 6.x are not supported.
160504	Recording	SD card recording can only be used when the specific cameras have not configured a password for the service, user and live account.
167599	IVA	When using IVA flow, forensic search might show an incomplete overview of results.
167626	Authentication	When the "user" or "live" user account is configured with an empty password, it is possible to see a live video despite the "service" user password is wrong.
165065	MVS	When using an iPhone SE, the mobile application crashes when trying to send live video to other mobile operators.
163927	VRM	When adding and importing a Video Recording Manager, with an DSA e-series and multiple ports, some ports may not be added.
160929	Configuration	It is recommended to add the MIC 550 (using the IP power supply) manually and configuring the device "MIC VIP" explicitly, instead of scanning it.
160536	Maps	The map cannot be panned outside of the limits of the CAD graphic. Centering on a hotspot will behave different compared to earlier versions.
164767	Authentication	When configuring the "service" password of a camera, the "live" and "user" password needs to be configured as well.
151049	ANR	ANR playback will not work when a camera is configured to use the HTTPS protocol to communicate with the BVMS.
145023	VRM	The Video Recording Manager service will be restarted when the physical network adapter is online, after it has been offline.
154913 153044	Maps	Due to map loading times, it is recommended to not use more than 1000 hotspots in maps that are configured for alarm scenarios. <ul style="list-style-type: none"> <li>• 500 hotspots: 1.5 seconds</li> <li>• 1000 hotspots: 2.5 seconds</li> <li>• 2000 hotspots: 5 seconds</li> <li>• 3000 hotspots: 9.5 seconds</li> <li>• 4000 hotspots: 14.5 seconds</li> </ul>
156105	Transcoding	Videojet XTC Transcoder not longer supported
167598	Transcoding	For hardware transcoding in BVMS 7.5 the latest transcoder firmware must be installed
165214	Maps	In rare circumstances the hotspots on a CAD graphic might flicker, when moving a map

# 5 Bosch Video Management System Version 7.0

## 5.1 Introduction

The latest version of the Release Notes is always available on the Bosch Product Catalog ([www.boschsecurity.com](http://www.boschsecurity.com)). Version 7.0 introduces new features and resolved issues to your Bosch Video Management System.

## 5.2 New features

ID	Description
n/a	Video authentication based on 2048 bit public/private key certificates
n/a	Automated stream switching for live streams
n/a	Encryption of communication from the camera to: operator client; VRM; management server.
n/a	Simple motion search
n/a	Unmanaged sites: support for different time zones
n/a	Unmanaged sites: VSG camera support

## 5.3 Installation Notes

For system design specifications refer to the Bosch VMS datasheet, Configuration Manual, pre-sales guide and Quick Installation Guide on <http://www.boschsecurity.com>. The datasheet is subject to change. Translated versions are not published instantly, for the latest version refer to the English version.

The installation manual and additional documentation of Bosch DSA E-Series iSCSI disk arrays can be found in Bosch on-line product catalogue on <http://www.boschsecurity.com>.

## 5.4 Firmware

Component	Version
VideoSDK	5.92.0052
Firmware MPEG-4	4.15.02
Firmware CPP3	5.73.0046
Firmware CPP4	6.21.0008 / 6.32.0099 / 6.44.0027
Firmware CPP5	5.92.0029
Firmware CPP6	6.21.0008 / 6.32.0099 / 6.44.0027

Component	Version
Firmware CPP7	6.21.0008 / 6.32.0099 / 6.44.0027
Firmware CPP7.3	6.44.0027
Firmware CPP-ENC	5.52.15(for VIP X1600 XFM4)
Firmware CPP-ENC	5.93.0023(for VJT XF E family, VIDEOJET decoder 3000)
Firmware X1/X2	2.53.05
VIP XD HD	1.8.1
VDJ 7000	54.8.2
VDJ 8000	8.10
VRM	3.55.0010 / 3.60.0043
VSG	6.17.0064
iOS	7.1.1 / 8.3 / 9.0.2
Web Client	11.0.96
BIS	4.0 / 4.1
Bintelan Analytics Platform	5.7.5955.25388
DiBos	8.7
BRS	8.10/8.11 / 5.92.0052
Allegiant MCS	2.94
Intuikey Keyboard	1.96
VMWare	5.1.0
DVR	2.3.2 / 3.60
Operating systems Operator Client	Windows 8.1 64-bit; Windows 10 64-bit anniversary update
Operating systems Config Client	Windows 7 Professional or Ultimate SP1 64-bit; Windows 8.1 64-bit; Windows 10 64-bit; Windows Server 2008 R2 SP1 64-bit; Windows Server 2012 R2 64-bit

Component	Version
Operating systems Management Server, Mobile Video Service	Windows 7 SP1 and 8.1 64-bit; Windows Server 2008 R2 SP1 64-bit; Windows Server 2012 R2 64-bit
Cameo SDK	1.3.0.0
BVMS SDK	1.9.0.0

## 5.5 Hardware

### Hardware requirements

For the HW-requirements of other components like VRM, VSG, Allegiant MCS – Please refer to the documentation of these components

Component	Version
Broadcom NetXtreme Gigabit	river for Microsoft Windows 7 and Windows 8.1 (64 bit) 16.8.4.1 Rev. A (14 Jan 2015)
Intel PRO-1000 Gigabit	Driver for Microsoft Windows 7 and Windows 8.1 (64 bit): R19_338993 Rev.M (2 Feb 2015)
NVIDIA Quadro	Driver for Windows 7 and Windows 8.1 (64-bit): 347.52 Rev.A (12 Feb 2015)
ATI FireGL	Unified Graphics Driver for Microsoft Windows 7 and Windows 8.1 (64-bit): 14.301.1014.1001 Rev.A (9 Feb 2015)

## 5.6 Resolved issues

ID	Description
133129	<b>FIXED:</b> In some rare cases it can happen that the export of video data from a DVR 700 does not work correctly.
145423	<b>FIXED:</b> When upgrading to Bosch VMS 6.5.0.325 on a system where there is a Barco Monitor Wall or a Bosch Monitor Wall configured, execute the following steps to avoid a Central Server crash during startup of the service:- Perform the upgrade to Bosch VMS 6.5.0.- Install Patch 145423 - Migration issue.For later Bosch VMS versions, this issue is resolved.

## 5.7 Known issues

ID	Description
151294, 151296	Multiple domes connected to the same encoder cannot be controlled by more than one client simultaneously
144104	When a multi-channel encoder is used in Ganetec Bintelan, only video of the first camera will be used for analytics, even if the other cameras are being selected and configured.
148394, 152880	Direct iSCSI playback is not supported when using the Video Recording Manager large LUN feature.

ID	Description
145182	When upgrading the Video Streaming Gateway the message "" needs to be confirmed.
155234	When using the Enterprise Operator Client video by event search: when the video by event dialog is opened and the time zone is changed, the time does not change accordingly in the events that are already listed.
155234	When using the Enterprise Operator Client logbook: when the logbook dialog is opened and the time zone is changed, the time does not change accordingly in the logbook items that are already listed.
154765 / 154667	<p>If Microsoft patch 3155464 is installed, Bosch VMS is not able to communicate to the intrusion panels GV4, B-Series US1B or B-Series US1A. Bosch VMS does not receive events and alarm from the panels and cannot control the intrusion panel. To avoid this issue the panel firmware of B-Series US1B and G-Series US1A has to be upgraded to version 3.03.014. In case of GV4 panels the Microsoft patch 3155464 could be disabled via recommended Microsoft procedure: <a href="https://support.microsoft.com/en-us/kb/3155464">https://support.microsoft.com/en-us/kb/3155464</a></p> <p><b>Warning:</b> These workarounds may make a computer or a network more vulnerable to attack by malicious users or by malicious software such as viruses. We do not recommend these workarounds but are providing this information so that you can implement these workarounds at your own discretion. Use these workarounds at your own risk.</p>
153951	Unprotect / delete video will not work when the Operator Client is connected through a routed access environment.
142499	Authenticity check is not implemented for DIVAR AN 3000 and DIVAR AN 5000.
150009	VIDEOJET 7000/8000 does not support audio playback.
155415	When a DIVAR AN 3000 or DIVAR AN 5000 is added in unmanaged sites, the properties of the playback cameo do not contain the date and time.
143823	Instant playback may show a black cameo if an instant playback value of less than 10 seconds is configured.
147027	When Windows 10 64-bit is used as the operating system for the management server (which is not supported), the "Bosch VMS DVR Adapter" and "Bosch VMS Web Service Host" services are not started automatically.
149922	When exporting video with changing FPS rates (for example, due to alarm recording), display of the framerate is only correct if you use Windows Media ASF viewer.
n/a	When using the Bosch VMS in a Hyper-V environment, the latest (network-card) drivers need to be installed.
n/a	When using the Bosch VMS CameoSDK, frequent connect/disconnect can cause a memory leak. It is recommended to use a permanent connection when using the CameoSDK.
n/a	When using the VRM 3.60 large lun feature, primary and secondary VRM have to have the same configuration of the LUN size.
142145	When removing a camera from the configuration, and later adding it again, Ganetec Bintelan will lose its relation to that specific camera. The camera then also needs to be reconfigured in Ganetec Bintelan.
144940	When using the remote Operator client, video export from devices added as a DVR will not work.
152454	When a completely configured VRM is added to the Bosch VMS configuration, Bosch VMS will overwrite the camera names with default values.

ID	Description
148551	When replacing an encoder the new encoder does not record any more. The camera has to be deleted from the Bosch VMS configuration and added again. The recording will continue and previous recordings will be available.
162254	When the installation of the .NET framework 4.6.1 fails, <a href="#">KB2919355</a> needs to be installed prior to installing the Bosch VMS.

# 6 Bosch Video Management System Version 6.5

## 6.1 Introduction

The latest version of the Release Notes is always available on the Bosch Product Catalog ([www.boschsecurity.com](http://www.boschsecurity.com)). Version 6.5 introduces new features and resolved issues to your Bosch Video Management System.

## 6.2 New features

ID	Description
133588	Integration of Bintelan video analytics viewer
129290	Add Bosch VMS to an unmanaged site
136706	ZIP export (export to a single file)
126571	Config Wizard improvements
142747	Controls for panoramic view mode in Image pane

## 6.3 Installation Notes

For system design specifications refer to the Bosch VMS datasheet, Configuration Manual, pre-sales guide and Quick Installation Guide on <http://www.boschsecurity.com>. The datasheet is subject to change. Translated versions are not published instantly, for the latest version refer to the English version.

The installation manual and additional documentation of Bosch DSA E-Series iSCSI disk arrays can be found in Bosch on-line product catalogue on <http://www.boschsecurity.com>.

## 6.4 Firmware

Component	Version
VideoSDK:	5.92.0052
Firmware MPEG-4:	4.15.0002
Firmware CPP3:	5.73.0046
Firmware CPP4:	6.21.0008
Firmware CPP5:	5.92.0029
Firmware CPP6	6.21.0008
Firmware CPP-ENC	5.52.0015 (for VIP X1600 XFM4)
Firmware CPP-ENC	5.93.0023 (for VJT XF E family, VIDEOJET decoder 3000)

Component	Version
Firmware X1/X2:	2.53.05
VIP XD HD	1.8.1
VJD 7000	54.8.2
VDJ 8000	8.10
VRM:	3.55.0010
VSG	6.17.0064
DiBos	8.7
BRS:	8.10 / 8.11
BIS:	4.0 / 4.1
iOS:	7.1 / 8.3 /9.0.2
Web Client	IE 11
Allegiant MCS:	2.94
Intuikey Keyboard:	1.96
VMWare:	5.1.0 U1 build 1065491
DVR	2.3.2 / 3.60
Bintelan Analytics Platform	5.7.5955.25388
Operating systems Operator Client	Windows 7 Professional or Ultimate SP1 64-bit and Windows 8.1 64-bit
Operating systems Config Client. Management Server, Mobile Video Service	Windows 7 SP1 64-bit; Windows 8.1 64-bit; Windows Server 2008 R2 SP1 64-bit; Windows Server 2012 R2 64-bit
Cameo SDK	1.3.0.0
BVMS SDK	1.9.0.0



## 6.5 Hardware

### Hardware requirements

For the HW-requirements of other components like VRM, VSG, Allegiant MCS – Please refer to the documentation of these components

Component	Version
Broadcom NetXtreme Gigabit	river for Microsoft Windows 7 and Windows 8.1 (64 bit) 16.8.4.1 Rev. A (14 Jan 2015)
Intel PRO-1000 Gigabit	Driver for Microsoft Windows 7 and Windows 8.1 (64 bit): R19_338993 Rev.M (2 Feb 2015)
NVIDIA Quadro	Driver for Windows 7 and Windows 8.1 (64-bit): 347.52 Rev.A (12 Feb 2015)
ATI FireGL	Unified Graphics Driver for Microsoft Windows 7 and Windows 8.1 (64-bit): 14.301.1014.1001 Rev.A (9 Feb 2015)

## 6.6 Resolved issues

### 6.6.1 Operator Client

ID	Description
123311	<b>FIXED:</b> Operator Client does not properly display HTML 5 documents.If you require HTML 5, install IE11, and add the following registry key: HKEY_LOCAL_MACHINE\SOFTWARE\Wow6432Node\Microsoft\InternetExplorer\MAIN\FeatureControl\FEATURE_BROWSER_EMULATIONDWORDs and Values:OperatorClient.exe 11001 (decimal)ConfigClient.exe 11001 (decimal)
133803	<b>FIXED:</b> Export: When remote export contains a transcoded stream, the full non-transcoded stream will be exported despite a warning message indicating, that the respective camera will not be included in Export. This may lead to the export taking a very long time.

### 6.6.2 Configuration Client

ID	Description
133283, 134182	<b>FIXED:</b> Client scripts: It is not possible to reference cameras of an unmanaged site in a client script on Operator Client which only contains unmanaged sites.
134412	<b>FIXED:</b> When importing a configuration file from an earlier Bosch VMS version (<= 5.5.8), the intrusion panel structure nodes and ONVIF are shown even if the event nodes are not generated yet. As always after upgrade and import of earlier configuration files please activate and restart CC to display new event types.
128794	<b>FIXED:</b> When using high resolution cameras with the default bitrate, please adapt the I-frame distance manually to 30 fps (instead of using "Auto" mode). Auto mode sets the I-frame-distance to 10 which may affect the image quality.

## 6.6.3 Integration with ONVIF cameras

ID	Description
131697	FIXED: Only stateful events are supported in Bosch VMS. Stateless events of ONVIF cameras are not supported in Bosch VMS 6.0.
134164	FIXED: Camera capabilities/ parameters (vendor, etc...) are empty when adding ONVIF Encoder manually without pressing "Test".

## 6.6.4 MVS / Web Client

ID	Description
91783	<b>FIXED:</b> The following actions in Web Client are not logged:- Toggle relays, PTZ control, search for metadata; export videoFollowing user actions are logged: - Log on and log off.
135080	<b>FIXED:</b> When "Multiple logons for the same user" is disabled in the Configuration Client, the user has to properly use the "logout button". When the user just closes the web-client/App, the user is not able to log on to the system again for 5 minutes (connection time-out).

## 6.7 Known issues

### 6.7.1 Management Server

ID	Description
48584	Installation of Microsoft SQL Server does not work on a computer with a compressed C: drive ( <a href="https://connect.microsoft.com/SQLServer/feedback/details/704250/installation-failed-when-c-drive-compressed">https://connect.microsoft.com/SQLServer/feedback/details/704250/installation-failed-when-c-drive-compressed</a> ).

### 6.7.2 Integration with Ganetec Bintelan

ID	Description
142292	Due to a late change, the translated application help and the translated manuals give wrong information on the installation directory of the Analytics Viewer to be installed on each desired Operator Client workstation. The correct installation directory is: C:%ProgramFiles(x86)%\VideoAnalytics\AnalyticsViewer.exe
142292	When the application runs in an environment, where alarms are sent to Bosch VMS in high frequency (for example, number plate detection at a highway) and the server is shut down for a longer period, the following effects occur when MS is back: All queued alarms are pushed to the Alarm List of Operator Client, until the max. limit of 1.000 is reached. The server then automatically and successively clears the oldest entries to prevent overload. This may take several minutes. Alarms are logged in the Logbook.

## 6.7.3 Upgrade

ID	Description
145423	If you upgrade to Bosch VMS 6.5.0.325 on a system where you have configured a Barco Monitor Wall or a Bosch Monitor Wall, execute the following steps to avoid a Central Server crash during startup of the service:- Perform the upgrade to Bosch VMS 6.5.0. - Install Patch 145423 - Migration issue. For later Bosch VMS versions, this issue is resolved.

## 6.7.4 Video Recording Manager

ID	Description
138712	Bosch VMS cannot import a VRM configuration that was created on DIP 2000 with camera types newer than this DIP 2000.

## 6.7.5 Bosch VMS SDK

ID	Description
137501	When the SDK-method <code>Api.CameraManager.StartAlarmrecording</code> is called with a default <code>Object()</code> for parameter <code>metadata</code> set to an empty string, an empty string is frequently logged in the Operator Client log file.

## 6.7.6 Routed access

ID	Description
144848, 135108	Audio is not supported via routed access.

## 6.7.7 Configuration Client

ID	Description
143590	The <b>Unknown</b> state event was added as the new default state to the relays and inputs Event tree. In earlier Bosch VMS versions, the <b>Error</b> state event was the default state.

## 6.7.8 Operator Client

ID	Description
136426	Due to changes in MS Windows 8.1 the user cannot add further sessions to a multisession media (DVD, Blue-Ray, CD). Please use blank media only.
136419	Under some circumstances writing an export to read write media disks fails. We recommend using non-RW media.
139354	Using unmanaged site access, Operator Client ignores the operating permissions configured in the unmanaged Bosch VMS.

## 6.7.9 Setup

ID	Description
145248	Under certain circumstances an error message box can be displayed during update installation from Bosch VMS 6.0 to 6.5 saying "Directory is not empty". Click <b>Retry</b> . The Setup continues and the update installation is successfully finished.
145182	Under certain circumstances, the old VSG service can display an error message. Close this error message box, ensure that the VSG service is stopped and continue with Setup.
143995	The No Touch Deployment - Setup takes longer due to upgrade to the new .NET version, and this upgrade requires manual interaction.
142316	For the following camera types it is not possible to ensure that the playback of multiple cameras remains synchronous for a longer time period:- DVR - Transcoded video

## 6.7.10 Integration with ONVIF cameras

ID	Description
127689, 136270	Base notification for ONVIF devices is not supported.
138567	Switching relays of ONVIF devices is currently not supported by Bosch VMS, although relays of ONVIF cameras are displayed in the UI of the Web Client. The relays appear to be switchable in the Web Client, but this switching has no effect on the device.
144020	Cameras connected to VSG do not show connect / disconnect status but video loss instead.

## 6.7.11 VSG

ID	Description
133840	VSG section: In case of disconnect VSG is recording the video containing "video loss" - icon. Hence the red recording overlay icon is displayed.

## 6.7.12 Miscellaneous

ID	Description
140604	A fire / smoke alarm of an AVIOTEC camera always sends also a motion alarm.
145190	The Search tab of an opened CHM file on a Windows 7 64-bit OS with Arabic display language is fragmented. You can enter a search term and start the search but this not visible (see KB article 2021383).
150009	VJD7000/8000 does not support audio when configured and used in Bosch VMS.
147859	A multi client operation of PTZ cameras is not supported for domes on the same interface.

# 7 Bosch Video Management System 6.0

## 7.1 Introduction

The latest version of the Release Notes is always available on the Bosch Product Catalog ([www.boschsecurity.com](http://www.boschsecurity.com)). Version 6.0 introduces new features and resolved issues to your Bosch Video Management System.

## 7.2 New features

- 3<sup>rd</sup> party camera integration
  - Onvif Mapping Files with predefined event mapping of ONVIF Cameras to BVMS events
  - Configuration of camera settings from within Configuration Client
  - 3<sup>rd</sup> party camera integration
- Unmanaged Site concept
  - to connect to cameras of up to 9.999 sites
  - with simultaneous connections to up several sites
  - for live&playback of DVR + DIVAR AN series
- Map features:
  - Advanced state display
  - thumbnails at mouse over
  - accept clear alarms on hotspot
  - Access pre-positions from hotspot
- Intrusion panel:
  - Support output
  - Support doors
  - Support of points
  - Silence areas
- Security related:
  - Prevent same user to log on to different Operator Client workstations
  - Enforce secure password (configurable)
  - Configurable alarm at "manually delete video"
  - Tamper proof export (encrypted with digital signature)
  - Configuration backup (scheduled and manual via SDK)
- Wizard:
  - Assign cameras to logical tree
  - Camera preview
  - Configurable Quality Profiles
  - Configurable Motion Recording
- Native integration of DIVAR AN 3000/5000
- Export of Configuration Reports
- Operator Client: Manual stream selection for live video
- Monitor Wall: Support of initial sequence (call up salvos)

## 7.3 Installation Notes

For system design specifications refer to the Bosch VMS datasheet, Configuration Manual, pre-sales guide and Quick Installation Guide on <http://www.boschsecurity.com>. The datasheet is subject to change. Translated versions are not published instantly, for the latest version refer to the English version.

The installation manual and additional documentation of Bosch DSA E-Series iSCSI disk arrays can be found in Bosch on-line product catalogue on <http://www.boschsecurity.com>.

## 7.4 Firmware

Component	Version
VideoSDK:	5.90.0084
Firmware MPEG-4:	4.15.0002
Firmware CPP3:	5.73.0046
Firmware CPP4:	6.11.0021
Firmware CPP5:	5.92.0026
Firmware CPP6	6.11.0021
Firmware CPP-ENC	5.52.0015 (for VIP X1600 XFM4)
Firmware CPP-ENC	5.93.0015 (for VJT XF E family, VIDEOJET decoder 3000)
Firmware X1/X2:	2.53.05
VIP XD HD	1.8.00
VJD 7000	54.8.1
VRM:	3.50.0042
VSG	6.17.0051
DiBos	8.7
BRS:	8.10 / 8.11
BIS:	4.0 / 4.1
iOS:	7.1 / 8.3 / 9.0.2
Web Client	IE 11
Allegiant MCS:	2.94
Intuikey Keyboard:	1.96
VMWare:	5.1.0 U1 build 1065491

Component	Version
Operating systems Operator Client	Windows 7 Professional or Ultimate SP1; 64-bit and Windows 8.1 64-bit
Operating systems Config Client. Management Server, Mobile Video Service	Windows 7 SP1 64-bit; Windows 8.1 64-bit; Windows Server 2008 R2 SP1 64-bit; Windows Server 2012 R2 64-bit

## 7.5 Hardware

### Hardware requirements

For the HW-requirements of other components like VRM, VSG, Allegiant MCS – Please refer to the documentation of these components

Component	Version
Broadcom NetXtreme Gigabit	river for Microsoft Windows 7 and Windows 8.1 (64 bit) 16.8.4.1 Rev. A (14 Jan 2015)
Intel PRO-1000 Gigabit	Driver for Microsoft Windows 7 and Windows 8.1 (64 bit): R19_338993 Rev.M (2 Feb 2015)
NVIDIA Quadro	Driver for Windows 7 and Windows 8.1 (64-bit): 347.52 Rev.A (12 Feb 2015)
ATI FireGL	Unified Graphics Driver for Microsoft Windows 7 and Windows 8.1 (64-bit): 14.301.1014.1001 Rev.A (9 Feb 2015)

## 7.6 Resolved issues

### 7.6.1 Operator Client

ID	Description
n/a	<b>FIXED:</b> Anti-Aliasing effects in Image of Panoramic camera
n/a	Press Ctrl-button and drag&drop points of interest in panoramic view to empty cameo to get an additional cropped views
116840	<b>FIXED:</b> Operator Client restarted during update of the FW on VIP X16 XF E.
64470	<b>FIXED:</b> Under rare circumstances Operator Client unintentionally logs off and cannot log on automatically after a forced activation. This happens with higher probability in large systems with many Operator Client computers.
106003	<b>FIXED:</b> Sequencing black after switching

## 7.6.2 Configuration Client

ID	Description
93264	<b>FIXED:</b> Before deleting a device, please ensure that the Alarm List does not contain any alarms triggered by this device. Reason: The alarms cannot be cleared after the device is removed.
n/a	<b>FIXED:</b> Email servers with SSL/TLS were not supported.

## 7.6.3 Miscellaneous

ID	Description
133313	<b>FIXED:</b> [DIVAR 3000/5000] Refresh problem by displaying protected recording in the Timeline after protecting a time period of video.
125685	<b>FIXED:</b> IntuiKey keyboard (workstation keyboard) stopped working after forced configuration change.
129671	<b>FIXED:</b> In some rare cases MOV export did not export audio data.
118604	<b>FIXED:</b> SDK now also reflects the debounce settings when retrieving the current state.

## 7.7 Known issues

### 7.7.1 Integration with ONVIF cameras

ID	Description
134161	<ul style="list-style-type: none"> <li>The various manufacturers provide information on how to set up the camera so that it can be used as an ONVIF camera. This information can be found in the Interface Guide on the <a href="http://www.ONVIF.org">www.ONVIF.org</a> website.</li> <li>The ONVIF-implementation has been reworked in Bosch VMS in order for the Client to be more robust and tolerant. This may though lead to changed behavior with existing installations containing ONVIF cameras already. If you have already some ONVIF cameras connected to former Bosch VMS (&lt;6.0) and you cannot find them in the Bosch VMS 6.0 list (Bosch VMS IPP Web-page), please verify the functions on a Bosch VMS 6.0 Test-system first before you upgrade a system on the customer site.</li> <li>The limits regarding the mapping of ONVIF files are described in the Bosch VMS Pre-sales guide.</li> <li>Configuration of ONVIF cameras from within Bosch VMS Configuration Client offers a wide range of settings to configure ONVIF cameras in accordance with the ONVIF Standard. It is though not ensured, that all cameras support the configuration, since the scope is subject of the implementation of the standard in each ONVIF Camera model.</li> <li>Any message "Bad request" during configuration of ONVIF cameras means that the camera refused the entered value or data. Please contact the camera vendor for support.</li> </ul>
134164	Camera capabilities/ parameters (vendor, etc...) are empty when adding ONVIF Encoder manually without pressing "Test".
134846	Every change on ONVIF Configuration pages (on a device) requires re-browsing the camera capabilities and profiles. Please configure an ONVIF camera EITHER as VSG camera OR as Live-only camera, but do not use both modes for the same camera, as this may lead to toggling connect/disconnect status



ID	Description
131697	Only stateful events are supported in Bosch VMS. Stateless events of ONVIF cameras are not supported in Bosch VMS 6.0.
134184	When an ONVIF camera that is connected to a VSG gets disconnected, its behavior will be similar as analog cameras connected to encoder: Status changes to "Disconnected". The recording will continue.
n/a	The event "Video Loss" is used to indicate connection loss between digital encoder and analog camera. It is therefore not supported for IP cameras.
n/a	ONVIF events and configuration are specified via Port 80

## 7.7.2 Setup

ID	Description
129695	<p>Bosch VMS Setup cannot be used on DIVAR IP hardware. To upgrade DIVAR IP to 6.0 or later, the Setup provided on the DIVAR IP Product Catalog page has to be used. Workaround to allow the update to Bosch VMS on DIP systems with the Bosch VMS setup package. This workaround should only be used for test and demonstration purposes.</p> <ul style="list-style-type: none"> <li>Find the files BvmsDesktop.exe and BVMSDesktop.exe.config in the folder C:\Program Files (x86)\Bosch\VMS\bin and save them for later use.</li> <li>Execute the Bosch VMS Setup from the command line "Setup.exe /v"INSTALLONDIVARIP=1"</li> <li>After finishing the Setup, restore the 2 files</li> </ul>

## 7.7.3 Management Server

ID	Description
n/a	External Microsoft SQL servers are supported to be used for remote Logbook recording. The migration process itself is not supported and requires a trained Microsoft SQL database administrator.

## 7.7.4 Configuration Client

ID	Description
128794	When using high resolution cameras with the default bitrate, please adapt the I-frame distance manually to 30 fps (instead of using "Auto" mode). Auto mode sets the I-frame-distance to 10 which may affect the image quality.
129133	A separate single-logon group is necessary for mobile and Web Client users that are part of dual logon user group. Dual logon users cannot log on as single users.
129648	Automatic distribution of LUNs on multi-port iSCSI (eSeries) does not work correctly when a basic configuration is performed. Please remove the iSCSI device and add it again to your system. Then the LUNs are evenly distributed.
132077	A CSV file for importing unmanaged sites must be comma separated.
132276	When using VSG or transcoder, none of the connected devices shall have a GOP length exceeding 30 frames. VSG and transcoder are limited to 30 frame-GOPs in replay.

ID	Description
132309	Unmanaged sites: The connection string of an unmanaged site must contain a valid IP address without port, no DNS name.
132362	Unmanaged sites: We strongly recommend that you do not use MS Excel to import sites due to the following risk: The passwords have to appear in Excel in plain text. If you still want to proceed on behalf of your own risk, please take corresponding precautions to prevent the passwords being exposed to unauthorized personnel.
132366	The Configuration Reports contain the export of large parts of the configuration in CSV format. It had been implemented years ago for a large project and has now been merged to the Main Branch of Bosch VMS. The feature is "as is" and will not be further extended.
132369	When the user of Configuration Client exports a report of the device permissions into a folder that has more than 256 characters, the report cannot be saved but no error message is displayed.
133283, 134182	Client scripts: It is not possible to reference cameras of an unmanaged site in a client script on Operator Client which only contains unmanaged sites.
134412	When importing a configuration file from an earlier Bosch VMS version ( $\leq 5.5.8$ ), the intrusion panel structure nodes and ONVIF are shown even if the event nodes are not generated yet. As always after upgrade and import of earlier configuration files please activate and restart CC to display new event types.
134445	Configuration Client crashes on an Operating System with a non-Western calendar, for example Arabic for Saudi Arabia. Change the calendar of such a system to the Western calendar.

## 7.7.5 Operator Client

ID	Description
138660	Camera has a password but Red-lock is missing in Device Tree (also for earlier Bosch VMS versions where customer starts using cameras with firmware $\geq 6.20$ )
117655	Multiple operator client logons on the same machine using different Windows user accounts is not supported and may cause Operator Client crashes.
123311	Operator Client does not properly display HTML 5 documents. If you require HTML 5, install IE11, and add the following registry key: HKEY_LOCAL_MACHINE\SOFTWARE\Wow6432Node\Microsoft\InternetExplorer\MAIN\FeatureControl\FEATURE_BROWSER_EMULATIONDWORDS and Values:OperatorClient.exe 11001 (decimal)ConfigClient.exe 11001 (decimal)
128566	[DIVAR 3000/5000] Refresh problem by displaying protected recording in the Timeline after protecting a time period of video. Change zoom factor of the Timeline to refresh.
129590	The tree search in Tree View does not work for cameras of an unmanaged site. Search for sites works as expected.
132330	Exported video data in MOV format shows a delay between audio and video:- delay between sound and video after 10 min is 4 sec- delay between sound and video after 60 min is 20 sec- no delay at the beginning of the exported MOV file- audio is earlier than video
132331	When opening a ROI Camera, the context menu of an Image pane offers 'Save Preset' and displays an empty command list.

ID	Description
132466	When starting Operator Client as non-Windows Administrator and opening a map, the Autodesk Design Review Setup is started.
132908	It is possible to add unmanaged sites to "Favorites" only using drag and drop. It is not possible using the context menu of an unmanaged site.
134074	Protected recordings of a DVR AN 3000/5000 can manually be deleted.
132565	Jump to the oldest recording does not work on DIVAR AN 3000 and 5000.
133129	In some rare cases it can happen that the export of video data from a DVR 700 does not work correctly.
133803	Export: When remote export contains a transcoded stream, the full non-transcoded stream will be exported despite a warning message indicating, that the respective camera will not be included in Export. This may lead to the export taking a very long time.

## 7.7.6 Web-Client/IOS-App

ID	Description
135080	When "Multiple logons for the same user" is disabled in the Configuration Client, the user has to properly use the "logout button". When the user just closes the web-client/App, he is not able to logon to the system again for 5 minutes (connection time-out).

## 7.7.7 DVR/DIVAR AN

ID	Description
n/a	Permission to manually delete video is not activated per default in DVR. If this is required, please activate permission on DVR in order to be able to manually delete video from within Bosch VMS.
127735	Be aware that a running virus scanner can influence the DVR device scan result. Devices might be missing. To ensure a proper scan result, turn off virus scanner during scan, or add device manually.

## 7.7.8 Devices

ID	Description
118727	VIP-X1600X FM4 always uses stream 2 for the secondary VRM even although stream 1 has been configured.

## 7.7.9 Intrusion Panel

ID	Description
128572	When the intrusion panel is disconnected from Bosch VMS, the states of the outputs (relays) do not change to "unknown". Doors are inserted in the Device Tree as an independent item and not as a child item of an area (like a point).

ID	Description
131467	When a user of RPS performs changes on the states of areas, points or outputs, it can happen that these changes are not correctly indicated by the status icons for these devices in Operator Client. To synchronize RPS with Bosch VMS configuration please rescan intrusion panel devices in Bosch VMS after changes in RPS.
135738	When adding a B8152 or B9512 panel, the type of the panel is not displayed properly in the device tree. It shows "New panel" and IP-address. But the panel can be renamed.
135740	B9512 supports only 16 supervised Keypads in BVMS

## 7.7.10 Video Recording Manager

ID	Description
93780	Continuous recording: The entire block is protected. This can lead to an unexpected disk full state. Alarm recording: VRM supports a maximum number of 32 protected alarms per block. Consequently, if more alarms occur, alarm # 33 and above cannot be protected.
122634	VRM cannot be configured on an All-In-One system with an already existing ATM/POS Bridge. First configure a VRM, then configure an ATM/POS bridge with the same IP address.
133096	VRM: When an encoder is deleted from the Primary VRM, the encoder password will also be deleted from the encoder.
152454	As of Bosch VMS 6.0, VRM 3.50 is supported. When you do not upgrade VRM to version 3.50 during the upgrade to Bosch VMS 6.0, recording continues but you cannot change the configuration of the old VRM. If you upgraded your VRM software to version 3.50, you must manually synchronize the Bosch VMS configuration.

## 7.7.11 Miscellaneous

ID	Description
128420	Do not exceed the Windows OS font-size setting of 100% to avoid the Bosch VMS UI being corrupted.
134551	Remote Desktop Connection to computers which run the Bosch VMS Operator Client is not supported.

# 8 Bosch Video Management System 5.5.8

## 8.1 Introduction

The latest version of the Release Notes is always available on the Bosch Product Catalog ([www.boschsecurity.com](http://www.boschsecurity.com)). Version 5.5.8 introduces new features and resolved issues to your Bosch Video Management System.

## 8.2 New features in 5.5.8

ID	Description
n/a	Device icons on maps (hot spots) can now display device states with background color and blinking if the corresponding state event is configured (Advanced State Display).
n/a	A client script can now trigger instant playback for a camera.

## 8.3 Installation Notes

For system design specifications refer to the Bosch VMS datasheet, Configuration Manual, pre-sales guide and Quick Installation Guide on <http://www.boschsecurity.com>. The datasheet is subject to change. Translated versions are not published instantly, for the latest version refer to the English version.

The installation manual and additional documentation of Bosch DSA E-Series iSCSI disk arrays can be found in Bosch on-line product catalogue on <http://www.boschsecurity.com>.

## 8.4 Firmware

Component	Version
VideoSDK:	5.83.0038
Firmware MPEG-4:	4.15.0002
Firmware CPP3:	5.73.0046
Firmware CPP4:	6.11.0021
Firmware CPP5:	5.92.0023
Firmware CPP6	6.11.0021
Firmware CPP-ENC	5.52.0015 (for VIP X1600 XFM4)
Firmware CPP-ENC	5.93.0015 (for VJT XF E family, VIDEOJET decoder 3000)
Firmware X1/X2:	2.53.05
VIP XD HD	1.8.00

Component	Version
VJD 7000	54.8.00
VRM:	3.00.75
VSG	5.91.0022
DiBos	8.7
BRS:	8.10 / 8.11
BIS:	3.0 / 4.0 / 4.1
iOS:	7.1 / 8.3
Web Client	IE 11
Allegiant MCS:	2.94
Intuikey Keyboard:	1.96
VMWare:	5.1.0 U1 build 1065491
DVR	2.1 / 3.60
Operating systems Operator Client	Windows 7 Professional or Ultimate SP1; 64-bit and Windows 8.1 64-bit
Operating systems Config Client. Management Server, Mobile Video Service	Windows 7 SP1 64-bit; Windows 8.1 64-bit; Windows Server 2008 R2 SP1 64-bit; Windows Server 2012 R2 64-bit

## 8.5 Hardware

### Hardware requirements

For the HW-requirements of other components like VRM, VSG, Allegiant MCS – Please refer to the documentation of these components

Component	Version
Broadcom NetXtreme Gigabit	river for Microsoft Windows 7 and Windows 8.1 (64 bit) 16.8.4.1 Rev. A (14 Jan 2015)
Intel PRO-1000 Gigabit	Driver for Microsoft Windows 7 and Windows 8.1 (64 bit): R19_338993 Rev.M (2 Feb 2015)
NVIDIA Quadro	Driver for Windows 7 and Windows 8.1 (64-bit): 347.52 Rev.A (12 Feb 2015)

Component	Version
ATI FireGL	Unified Graphics Driver for Microsoft Windows 7 and Windows 8.1 (64-bit): 14.301.1014.1001 Rev.A (9 Feb 2015)

## 8.6 Resolved issues in version 5.5.8

n/a

## 8.7 Known issues in version 5.5.8

ID	Description
126952	The printout or snapshot of a map shows all hotspots without background colour and those which are blinking with a rectangular frame.
125880	Advanced State Display is currently not supported for Enterprise Systems.
125270	The translated Application Help files do not contain descriptions of the Advanced State Display feature. The English Application Help does contain such descriptions.

# 9 Bosch Video Management System 5.5.5

## 9.1 Introduction

The latest version of the Release Notes is always available on the Bosch Product Catalog ([www.boschsecurity.com](http://www.boschsecurity.com)). Version 5.5.5 introduces new features and resolved issues to your Bosch Video Management System.

### Known issues

All known issues of all past releases, that were not addressed yet, have been added to this current version. They are structured according to topics. The order of the topics follows the alphabet.

## 9.2 New features in 5.5.5

New devices:

- Bosch FLEXIDOME Panoramic 7000 MP
- Bosch FLEXIDOME Panoramic 5000 MP
- Bosch AUTODOME IP 4000/5000
- Bosch DINION IP Ultra 8000
- Bosch EXTEGRA IP 9000 FX
- Bosch DSA E-series 2700
- RTCAM 8000
- RTCAM 7000S
- RTCAM 7000D
- RTCAM 7000S dome
- RTCAM 5000 dome
- RTCAM 5000 bullet
- RTCAM 7000D PTZ
- RTCAM 7000S PTZ

Others:

- Encryption of native Export
- Support of the new NetApp Controller E 2700 Series
- New features supported within the backwards compatibility:
  - Support of Favorites and Bookmarks
  - Control of relays
- ASF Export added as option again

## 9.3 Installation Notes

For system design specifications refer to the Bosch VMS datasheet, Configuration Manual, pre-sales guide and Quick Installation Guide on <http://www.boschsecurity.com>. The datasheet is subject to change. Translated versions are not published instantly, for the latest version refer to the English version.

The installation manual and additional documentation of Bosch DSA E-Series iSCSI disk arrays can be found in Bosch on-line product catalogue on <http://www.boschsecurity.com>.

## 9.4 Firmware

Component	Version
VideoSDK:	5.83.0038



<b>Component</b>	<b>Version</b>
Firmware MPEG-4:	4.15.0002
Firmware CPP3:	5.73.0046
Firmware CPP4:	6.10.0129
Firmware CPP5:	5.92.0023
Firmware CPP6	6.10.0129
Firmware CPP-ENC	5.52.0015 (for VIP X1600 XFM4)
Firmware CPP-ENC	5.93.0015 (for VJT XF E family, VIDEOJET decoder 3000)
Firmware X1/X2:	2.53.05
VIP XD HD	1.8.00
VJD 7000	54.8.00
VRM:	3.00.75
VSG	5.91.0022
DiBos	8.7
BRS:	8.10 / 8.11
BIS:	3.0 / 4.0 / 4.1
iOS:	7.1 / 8.3
Web Client	IE 11
Allegiant MCS:	2.94
Intuikey Keyboard:	1.96
VMWare:	5.1.0 U1 build 1065491
DVR	2.1 / 3.60
Operating systems Operator Client	Windows 7 Professional or Ultimate SP1; 64-bit and Windows 8.1 64-bit

Component	Version
Operating systems Config Client. Management Server, Mobile Video Service	Windows 7 SP1 64-bit; Windows 8.1 64-bit; Windows Server 2008 R2 SP1 64-bit; Windows Server 2012 R2 64-bit

## 9.5 Hardware

### Hardware requirements

For the HW-requirements of other components like VRM, VSG, Allegiant MCS – Please refer to the documentation of these components

Component	Version
Broadcom NetXtreme Gigabit	river for Microsoft Windows 7 and Windows 8.1 (64 bit) 16.8.4.1 Rev. A (14 Jan 2015)
Intel PRO-1000 Gigabit	Driver for Microsoft Windows 7 and Windows 8.1 (64 bit): R19_338993 Rev.M (2 Feb 2015)
NVIDIA Quadro	Driver for Windows 7 and Windows 8.1 (64-bit): 347.52 Rev.A (12 Feb 2015)
ATI FireGL	Unified Graphics Driver for Microsoft Windows 7 and Windows 8.1 (64-bit): 14.301.1014.1001 Rev.A (9 Feb 2015)

## 9.6 Known issues in version 5.5.5

ID	Description
45004	When activating a license of the Operating System, make sure that the network adapters required for operation are active. When unplugging a network cable, these Operating Systems deactivate the corresponding network adapter.
48584	Upgrade is not working if Configuration Client is left open - close Configuration Client before upgrade.

## 9.7 Resolved issues in version 5.5.5

ID	Description
111627	FIXED: A DIVAR 700 added to Bosch VMS, has a video quality issue in Live Mode.

## 9.8 Restrictions panorama camera

ID	Description
117194	<ul style="list-style-type: none"> <li>• Edge dewarping (Application Variant modes) not supported, since more flexible Client dewarping is in place.</li> <li>• Keyboard control: <ul style="list-style-type: none"> <li>• Intuikey keyboard: No E-PTZ in playback, Jog shuttle supported.</li> </ul> </li> </ul>

ID	Description
108160	<ul style="list-style-type: none"> <li>• Export: Only circled view is exported               <ul style="list-style-type: none"> <li>• To view dewarped video, open native export with Operator Client or Archive Player.</li> </ul> </li> <li>• Presets not supported (therefore presets cannot be used for alarm pop-ups, but always shows panorama view)</li> <li>• Circled view only is shown in               <ul style="list-style-type: none"> <li>• Digital Monitor Wall control</li> <li>• Display of VIDEOJET decoders (Monitor Wall)</li> <li>• Web client/iOS App</li> <li>• Transcoded video (SW-/and HW-transcoded)</li> <li>• Reference image</li> </ul> </li> <li>• Forensic search:               <ul style="list-style-type: none"> <li>• IVA overlays are not displayed in Operator Client. However, Forensic search is working fine.</li> <li>• Smart IVA search is not supported.</li> </ul> </li> </ul>

## 9.9 Known issues since version 1.0

### 9.9.1 ANR

ID	Description
116689	When configuring ANR for multi-channel encoders, it is only possible to configure ANR for all encoder channels (not for selected channels only).
93344	Please refer to the Release Notes and the Whitepaper of ANR to find out about the known limits. These documents are available in the documents' section of the IP cameras in the Bosch product catalog in the Internet.
93272	A "buffered storage state" alarm might also indicate a missing or broken SD-card.
81663, 79824	ANR feature does not show playback if user/live password is set.
80033	The time of an SD card 100% fill level warning event is not the point in time when the recording gap is starting or ending.
n/a	As of firmware version 6.10 the procedure for configuring the local storage of an encoder for use with ANR has been changed.
n/a	Use of ANR applies to the platforms CPP6, CPP4 and CPP-ENC with Firmware version 5.90 or later.

### 9.9.2 ATM/POS

ID	Description
111280	To get ATM/POS working under Windows 2012 server R2, the following needs to be done: Deactivate the ECN Capability setting on Windows 2012.

## 9.9.3 Barco Monitor Wall Transform N

ID	Description
n/a	<p>New RCP+ Agent has been introduced as of Bosch VMS 4.5.5 to integrate the Barco Transform N series. Barco RCP+ SDK Agent requires activation of multicast in all used cameras.</p> <p>Known issues:</p> <ul style="list-style-type: none"> <li>• Transform N series is in some cases not working with Bosch VMS 5.5.5. Previous version of Bosch VMS 5.5.1 is not affected. The issue is currently under investigation. Customers using transform N series are therefore recommended to stay on Bosch VMS 5.5.1 until the issue is fixed. Transform A series is not affected.</li> <li>• No multiple drag and drop support (sequences)</li> <li>• No replay support</li> </ul>

## 9.9.4 CameoSDK, Client scripts

ID	Description
105817	Most client scripts are not supported when Operator Client is connected to a Management Server with a previous version.
103044	When a user with restricted rights to access all cameras, executes a client script (via Logical Tree) that calls CameraManager.GetCameraInfoList(), ALL cameras are returned, not only those, the user has access rights for.

## 9.9.5 Configuration Client

ID	Description
93264	Before deleting a device, please ensure that the Alarm List does not contain any alarms triggered by this device. Reason: The alarms cannot be cleared after the device is removed.
93247	Adding a failover VRM does not work, when the VRM's license is expired. Workaround: Add the VRM as regular VRM (it is then licensed by BVMS), remove it and add it as failover VRM.
69440, 42654, 69438	Local storage devices do not support transcoding and no routed access.
68263	Activate the configuration manually after importing a configuration file from a previous Bosch VMS version.
51698	In Configuration Client you enter encoder names with more than 31 characters. But the encoder cannot store more than 31 characters, the name is truncated without warning.
37384	When using the Initial Device Scan to assign new IP addresses for new devices, ensure to not configure duplicate IP addresses.
35506	When configuring a Workflow alarm, do not use links containing a URL.

## 9.9.6 Config Wizard

ID	Description
80166	Config Wizard applies the global default password also to the VSG, but only if it is allocated to Pool 0.

## 9.9.7 Decoders

ID	Description
116807	OSD not possible with VJD-7000 Software based decoders (XDHD/VJD7000) do not support RCP commands required for OSD.
101898	The setting "use any stream" is used as default, but not supported for older VIPXD decoder.
69772	Monitor Wall reports "Layout changed" for all connected monitors, even when only one monitor layout was changed.

## 9.9.8 Devices

ID	Description
116593	IP devices already added to a DVR do appear again in device scan of VRM.
111627	A DIVAR 700 added to Bosch VMS, has a video quality issue in Live Mode.
93061	The following requirements must be met to configure ROI on the Cameras & Recording table:- Codes for stream 2 must be a ROI codec.- Stream 2 must be used for Live.- No recording configured for stream 2.
90740	On PTZ and ROI camera Image panes, the MD icon is not visible when video content analysis is enabled. The feature is working as expected.
85257	DVR 480 delivers images, which are horizontally stretched by approximately 20%.
78802	VIP X16 XF E has been moved to Device Family 2 for support of 2 <sup>nd</sup> stream for recording. Deviating from the behavior of the other devices belonging to Device Family 2, VIP X16 XF E must use the same stream for all recordings. Although the user can configure stream 1 for continuous recording and stream 2 for alarm recording, the second setting will not take effect. After a Bosch VMS upgrade, perform the update of the device family manually. <b>To update the device family:</b> Right-click the device and click <b>Edit Encoder</b> . Click <b>OK</b> .
70218	DVR 700 does not support verifying authenticity for attached cameras.
69503	The first firmware update of a VIP XD HD reports a false error. The update is nevertheless successful. Please perform the update twice. The second update is executed without error message.
69455	VIP X16 XFE does not support VCA manipulation and Reference Image events.
69285	You can add a DVR device without using the DIVAR Admin account.
n/a	As of Bosch VMS 5.0, 3rd party cameras can now be integrated via RTSP stream or MJPEG. Supervision of connection state and PTZ is not supported though.

## 9.9.9 Hardware transcoding

ID	Description
69798	Transcoded Image pane keeps last image at the end of recording instead displaying of blank image.

ID	Description
69774	Transcoding does not work with H.263 streams.
69451, 70813	Old FAS without wildcard support are not supported by transcoder.

## 9.9.10 Integration with GV4 and B-Series Intrusion Panels

ID	Description
104774	<p>Known behavior in Bosch VMS, yet new for the integration with intrusion panels:</p> <ul style="list-style-type: none"> <li>When Management Server is down or not up and running when an intrusion detection point is in alarm state, Bosch VMS is not able to display the alarm or get it later on.</li> <li>As it is not possible to retrieve the information on how many keypads are used, BVMS Configuration Client always shows the maximum number per default even if less are connected.</li> <li>To avoid missing that intrusion alarms are not logged, set the debounce time to 0.</li> <li>When a user enters a valid passcode a second time after access was already granted with this passcode, an error message is displayed in the keypad. But this error cannot be sent to Bosch VMS. (Note: Entering a wrong passcode is displayed in the Alarm List!).</li> </ul>
n/a	<p>Bosch VMS does <b>not</b> configure the panel, it only retrieves data.</p> <p>Avoid multiple connections with different tools to the same panel. When a panel is connected to Bosch VMS, you cannot establish a connection to this panel with RPS.</p> <p>Maximum number of panels connected to BVMS is <b>20</b>. Total event load of all panels must not exceed 100 events/minute.</p>

## 9.9.11 Intrusion panel

ID	Description
110545, 110582	When applying changes to panel points (e.g. using the "Copy to all" feature) on the event settings page it takes a very long time (minutes). Recommendation: Make changes in smaller portions, e.g. 200 at a time.

## 9.9.12 Management Server

ID	Description
93591, 68263	When a configuration from a previous Bosch VMS version is imported, new events that did not exist in the previous version, do not appear. To get the new events, you must manually activate the configuration and restart the Central Server service.
71354	If you use a Management Server with multiple network adapters, it can happen that the time synchronization of encoders and decoders does not work correctly. To avoid issues ensure that the IP address of the time synchronization server is configured in the Management Server configuration file (TimeServerIPAddress in the app-config file CentralServer.exe.config).
71354	Whenever you have two or more network addresses you need to make sure that the time server entry in the Management Server configuration is set to the correct IP address.

## 9.9.13 Migration

ID	Description
115289	Reference image: The default setting has changed with FW 6.10. The whole camera image is defined as sensitive area. Use Reference image mask to exclude areas that are irrelevant. Note: Tamper configuration of previous FW 5.93 is lost as soon as configuring a new area.
92820	Old elements.bvms (< 3.0.0) cannot be migrated if .NET 3.5 is not installed.
82945, 77484	For projects, that used dual recording or failover recording workaround prior to Bosch VMS 5.0: Respective licenses are needed per channel for dual recording and failover recording. Commercial solution might be requested from BU-ESS/MKP1.1 in case, that new licenses cannot be sold. After licensing, the VRM configuration needs to be imported into Bosch VMS by context menu on an empty VRM node in Configuration Client.
69514	Record AAC does not work. Encoders will automatically use G.711 to record audio.
n/a	NVIF cameras: After migration from an earlier version to Bosch VMS 5.0 or later, ensure that the firmware of the cameras is updated to the latest version. Otherwise it can happen that the cameras do not function correctly.

## 9.9.14 Miscellaneous

ID	Description
109562	Windows media player only capable to display UHD video exports, when K-lite codec pack is installed. .Alternatively use VLC player to view UHD camera exports.
102969	Bosch VMS pre-alarm default is set to be 10 seconds. When a user updates from a previous version to 5.5., the system behavior might change due to the fact that depending on the camera capabilities, the pre-alarm recording might now record in the RAM after update (thus not shown in Timeline any more).
91046	ASF exports are not possible for resolutions higher than HD (1920x1080).
85501	Debounce time for Virtual Input Data has been set to 0 to prevent losing events when used with additional data. Please set the debounce time to 0 when upgrading from an earlier version and using additional data.
76527, 77159	In previous BVMS version < 5.0 the "MON+CAM" commands referred to the logical numbers in Bosch VMS, not the numbers used by the Allegiant Matrix. This has been changed in BVMS 5.0. <a href="#">Instructions</a> for customers, that rely on the "wrong" previous behavior of "MON+CAM" and want to reactivate the former behavior (swapped parameters):  On the Management Server machine:  <ol style="list-style-type: none"> <li>1. Stop the Management Server service</li> <li>2. Open BvmsCentralServer.exe.config</li> <li>3. Uncomment line &lt;!----&gt; i.e. remove</li> <li>4. Save changed BvmsCentralServer.exe.config</li> <li>5. Start the Management Server service</li> </ol>
61586	If you configure both a local and an Enterprise user group each with LDAP, only the local LDAP user group can be used. The Enterprise user LDAP configuration is always ignored.
55737	Bosch VMS does not support an LDAP system with more than 1000 User Groups for LDAP servers supporting protocol version 2 only.

ID	Description
54600	If the number of entries in the Alarm List becomes too large (>1000), Operator Client runs possibly very slow.
28672	In Operator Client the permissions for sequences are ignored for sequences placed on maps.
20283	The user can access a sequence for which the permission was removed. This happens when the sequence has been saved as Favorite earlier.
n/a	Bosch VMS does not support B-frames. This may slightly reduce the image quality in the recording. If needed, please increase the bit rate in the profile settings in encoder to get the quality configured in the profile.
n/a	Allegiant CCL Emulation applies to IP cameras and decoders only.

### 9.9.15 MVS/Web-Client

ID	Description
93097	Restart the IIS after changing IP address of the Management Server computer for MVS.
92345	Restrictions of feature permissions for selected cameras do not work for Web Client and Mobile App. Only the restriction for the access is working correctly.
71820	Calling up cameras on a DIVAR 700 using the MVS is under some rare circumstances not always stable in playback.
68278	You cannot add an MVS in Configuration Client when the time between the Configuration Client computer and the MVS computer is not synchronized. Please ensure that the time is synchronized between the affected computers.
60527	If the IP address of a Management Server computer is changed during the MVS is offline, this new IP address is not transferred when the MVS becomes online again. Please perform a configuration change and activate. For example you can change the <b>Day</b> schedule.
n/a	Web-Client works well with IE 11. It has also been tested with Firefox 30, Chrome 36 and Safari 7.0.5. These versions show some limitations in the PTZ functionality of an Image pane.

### 9.9.16 NVR

ID	Description
91302	The Bosch VMS NVR is not supported by Windows 7 or 8.1 and thus not supported in Bosch VMS 5.0 anymore. VIDOS NVR is not supported in Bosch VMS 5.0 anymore.

### 9.9.17 ONVIF

Note: Many ONVIF features are optional and their availability depends on the feature set of the currently used ONVIF device.



ID	Description
105655	To set up ONVIF event mapping please adjust the ONVIF section in the BVMS log config file (%programfiles(x86)%\Bosch\VMS\AppData\Server\CentralServer\BVMSLogCfg.xml) to retrieve the needed values for the corresponding camera type. To avoid issues, please copy this file as backup and edit it then. Exchange „WARN" with „DEBUG".
102104	When you configure two ONVIF encoders with same IP but different credentials, the state icons in the Device Tree gets mixed up. Please ensure to provide consistent settings (for example credentials) for all instances of a single camera.
93295	Aux commands for focus and Iris is not yet supported for ONVIF cameras.
69417	Monitor wall does not support ONVIF.
69272	VIDEOJET Decoder 7000 supports ONVIF via VSG, VIDEOJET 3000 does not.
62505	For some ONVIF cameras, Operator Client only provides the prepositions that have been created on the cameras' web-page before.

## 9.9.18 Operator Client

ID	Description
116840	Operator Client will reboot in the course of updating the FW on VIP X16 XF E.
64470	Under rare circumstances Operator Client unintentionally logs off and cannot log on automatically after a forced activation. This happens with higher probability in large systems with many Operator Client computers.
117728	It is not possible to save an image on a PC without printer driver. Note: Windows 8.1 and 7 come with a printer driver pre-installed. In case Windows Storage Server 2012 is used, Operator can activate the Microsoft XPS Document Writer (without Administrator permissions).
110468	Encrypted export: Disable encryption in the export dialog if at least one camera of a Management Server running a previous Bosch VMS version has been selected.
106377	Under rare conditions with certain local security policies in place, Windows starts self repairing the Autodesk Review installation when Operator Client is started. In this case insert the Bosch VMS Setup DVD.
93193	Operator Client can terminate unexpectedly when camera sequences are running and the computer is locked, for example by pressing "Windows-key + L". Please avoid locking the computer when running sequences.
93019	Permission to use additional data does not work properly.
91166, 25200	The user can add the same camera to the Playback Image window. Bosch VMS allocates all available resources for decoding. This can significantly slow down the system.
73367	Playback is not possible in the hour after the second daylight saving time switch in each year.
71295	If clients are connected via low bandwidth, please do not force activation. The transfer of the new configuration can take very long time and no progress bar is displayed.
62207	An LDAP user can assign Allegiant cameras to AMG, but not clear them or assign another camera.

ID	Description
62970	Operator Client does not support Windows Guest account users.
45399	Disconnected OC will be logged by Management Server as "Logoff" instead of "Disconnected".
39834	At "Clear alarm" the user name could be missing in logbook.
30279	Manually triggered alarms (by user event buttons) with a higher priority are not ordered correctly in alarm list.
n/a	Operator Client now supports a "Multi-view" feature when watching live. This is particularly useful for displaying a 4K camera in multiple Image panes. The operator can then adapt the image section in each Image pane by using focus and zoom. The CPU load of Operator Client does not increase in this case. The reason is that the camera image is decoded only once, the image sections in the Image panes are not decoded again. The entire multi-view can be saved as a favorite. The multi-view feature is not supported for Playback Mode. In Playback Mode, an Image section of a camera is decoded for each Image pane. Displaying the recording of a 4K camera in multiple Image panes can lead to severe performance issues. The multi-view feature is not supported for transcoded videos.
n/a	When the connection of Operator Client to Management Server is reestablished after a period of working in offline mode, all user events that occurred during offline mode, are transmitted to the server. This is not valid for logon/logoff events. They are not logged during offline mode.

## 9.9.19 Panoramic cameras

ID	Description
113381	Platform Update for Windows 7 SP1 and Windows Server 2008 R2 SP1: MS KB 2670838 has to be installed for panoramic cameras.
n/a	User must not configure edge dewarping on the CMLib page of a panoramic camera, since client dewarping is used for the purpose of more flexible operation.

## 9.9.20 Bosch VMS SDK

ID	Description
71477	CameoSDK sample application: an unhandled exception is thrown when clicking "Disconnect" button.
69380	When a user with restricted rights to access all cameras, executes a client script (via Logical Tree) that calls CameraManager.GetCameraInfoList(), ALL cameras are returned, not only those, the user has access rights for.
69312	As of version 4.5.0 the DateTime objects returned by the ScheduleManager.GetScheduleStateTransitions() method have changed the value of the 'Kind' property from 'Unspecified' to 'Local'. Please ensure that your script logic is adapted accordingly.
61416	Use valid admin account only to connect via SDK to CS.

## 9.9.21 Search functions

ID	Description
105817,93460	<ul style="list-style-type: none"> <li>Archive Player does not support the search for text data.</li> </ul>
93510	When text exceeds 4000 bytes then the complete text block is not recorded (this may lead to no alarm being triggered).
93267	The <b>Find video by event</b> list always opens primary recording, even when search was run on secondary recording. Switch manually to secondary recording.
41145	When using <b>Find Video by event</b> , alarm recordings triggered by users cannot be found directly. You need to search for the general alarm recording and then sort by user.
80714	Forensic search is not possible when Operator Client is connected via routed access or on a transcoded stream.
69946	Video content analysis (IVA) on a transcoded Image pane is not supported.

## 9.9.22 Intelligent Video Analytics

ID	Description
116684	Description of selecting a VCA area is wrong as of FW 6.10. In the default setting, the whole camera image is defined as sensitive area. Use VCA masks to exclude disturbing objects or areas that are irrelevant for alarm event generation. Only objects moving outside VCA masks, in the sensitive area of the camera image, are detected as such and generate an alarm event. Objects moving inside VCA masks cannot generate an alarm event even if they are caught by the camera.

## 9.9.23 VIDEOJET connect 7000

ID	Description
117658	VIDEOJET connect can be used by Bosch VMS only with the corresponding variant type of the MIC IP 7000.

## Comments

- Ensure that the VIDEOJET connect 7000 and MIC IP 7000 have the same password settings to grant access to each other.
- To achieve local recording with VIDEOJET connect 7000, the configuration of storage needs to be done via the Configuration Manager. The local storage then appears with the IP of the VJC 7000 as iSCSI target in the Configuration Client.
- Transcoding and state supervision for VIDEOJET connect 7000 are not supported.
- Automatic Network Replenishment with VIDEOJET connect 7000 is working with a batch file issued for the devices' configuration.

## 9.9.24 Video Recording Manager

ID	Description
106169	Auto-protect recording does not work with CPP3 devices.

ID	Description
93771	Auto-protected recording on alarm: It may sporadically occur that the pre-alarm is not protected with the alarm. This is the case when pre-alarm and alarm are recorded on different recording blocks and only the later block is protected.
93162	In some rare cases, pre-alarm cannot be protected together with the alarm when pre-alarm is on the previous block.
93131	Auto-protected recording on alarm: The Timeline in Operator Client indicates exactly the time period that was selected for protection. But in fact the entire recording block is protected, which the protected time period belongs to.
93076	Auto-protect is not designed to be used with high frequency alarms. If alarms come in too frequently, this may lead to the last auto-protected recordings losing their protection. Technical background: If more than 32 auto-protected alarms occur on a single recording block, the 33 <sup>rd</sup> and following recordings will no longer be protected.
82703	When removing a VRM from the Bosch VMS configuration, ensure that this VRM is removed from the network before. Otherwise recording data might be lost.
30130	When the user of Configuration Client scans an existing VRM, the encoder names are renamed to default Bosch VMS names.

# 10 Bosch Video Management System 5.5

## 10.1 New features in version 5.5

- Support of intrusion panels from Bosch (B-Series, GV4-Series)
- Mapping ONVIF events to Bosch VMS events (for alarm handling)
- Support of the VIDEOJET connect 7000 with limited feature set when used with MIC IP 7000:
  - Supported: alarm inputs and outputs, audio in, washer relay, local recording and playback.
- ASF export is replaced by MOV export
- Export to multiple CD/DVDs
- Operator Client can work offline with a configuration of Bosch VMS version 5.0.5
  - First step of backwards compatibility Operator Client to Management Server
- Licensing available in Config Wizard, some GUI improvements
- Automatic logoff for Configuration Client
- VCA overlays are persisted in user settings
- Text data search conditions are persisted in user settings

# 11 Bosch Video Management System 5.0.5

## 11.1 Feature enhancements in version 5.0.5

### Operator Client

- FIXED: Display and search for additional text data did not work reliably. 93889

### Web-client

- FIXED: Display and search for additional text data did not work reliably. 93889

### Mobile Video Service (MVS)

- MVS adapted to better perform on HW with low performance.
- For better usability, the local MVS is shown in port mapping table with public port 443 and IP address of the DIVAR IP when using the Wizard.

# 12 Bosch Video Management System 5.0

## 12.1 New features in version 5.0

### 12.1.1 Devices

- Support of new Flexidome and Dinion 2000/4000/5000/7000/8000/9000 cameras series
- Support of MIC 550/612 and MIC 7000
- Support of VJD 3000 and 7000 including the support of 2 monitors
- Support of the Arecont AV8185DN 180°, live & playback, without stitching
- Support of the Rvision camera (legacy)
- Automated Network Replenishment
- Possibility to configure up to 7 different pre-alarms
- Region of Interest (ROI)
- Intelligent Tracking
- Support of new quality profiles
- Integration of the DTP3N (a German device to connect to ATMs)
- Integration of a Foyer Card Reader (Germany only)
- Malfunction relay (used to highlight a special event)
- Display of VBrick cameras on Monitor Wall
- Generic decoders added to AMG, differentiated between single and quad-view

### 12.1.2 Recording

- Dual recording and Failover VRM
- Support of up to 125 VRMs per Management Server, in LAN, with each VRM managing maximum 16 cameras.
- Automatically protected VRM recording on alarm
- Support of the E-series with dual controller
- User can select how many of the 7 instances of the VSG shall be installed
- VSG supports alarm recording triggered by BVMS events
- Backup LUNs/read only will not be overwritten anymore

### On-hold / Not-released

- Record, display and search for additional text data: *Although implemented in Bosch VMS 5.0, this feature is unfortunately not working 100% reliably yet. Known effects are, that search results are missing sporadically, and searching for/ playing back video with additional data may cause unexpected effects. This will be solved by a firmware upgrade and (if the circumstances require) a Bugfix release of a Bosch VMS version 5.0.x*

### 12.1.3 Operator Client

- Multi-view feature for live view: Select a camera multiple times without additional CPU-load
- Use of Software transcoding provided by the Mobile Video Service as a backup, when no hardware transcoder is available (live only)
- Inactivity Logoff with configurable time
- Operator Client automatically uses TCP protocol when connecting via routed access (despite any configuration and user settings)
- New operator group permission to allow the operator to change his password

### 12.1.4 Web-client

- Automatic setup of IIS (Mobile Video Service)
- Trigger relays
- Trigger export at Management Server
- Support of PTZ

- Web-Client UI available in several new languages

## 12.1.5 Mobile App

- New: Record video using the IOS mobile camera.
- Transmits videos to MVS server to share it with other staff members
- Notify and share live video with other security staff in emergency situation
- Notification provided in Web-client, when video is loaded to MVS server

## 12.1.6 Integration

- ONVIF provides status supervision
- Support of ONVIF cameras on Digital Monitor Wall (latest version)
- VSG supports audio for ONVIF cameras
- SNMP traps including MIB to other PSIM systems
- VSG supports RTSP and MJPEG (3rd party camera integration)
- New RCP+ Agent for Barco Transform N series
- Server SDK provides a sample application on how to BVMS broker to overcome the limitation of 2 subscriptions for server events.
- SDK is capable to dispose scripting objects on configuration change.
- Additional text data received by a BVMS event shows in the alarm list of the alarm

## 12.1.7 Miscellaneous

- VMware released with E-series
- Global security password to enforce password protection on all BVIP devices and secure the whole system
- Possibility to call up license manager in BVMS Configuration Client



# 13 Bosch Video Management System 4.5.9

## 13.1 New features in version 4.5.9

- Configuration Client and Configuration Wizard: To avoid security issues, a global default password must be set for all devices and all authorization levels (service, live, user) that are not password protected. You can disable this enforced password protection for BVIP devices.

# 14 Bosch Video Management System Version 4.5.8

## 14.1 New features in version 4.5.8

- User-defined columns can be added to the Server List.
- The Server List can be exported as csv file and imported again.
- For all cameras of a workstation you can configure that the default protocol used for network transmission is TCP or UDP. For a single camera you can override the default protocol.

# 15 Bosch Video Management System Version 4.5.5

## 15.1 New features in version 4.5.5

- New possibility to generically connect Bosch cameras: "Generically" means, that the Bosch encoders/decoders can be added firmware independently. Bosch VMS is able to retrieve the device capabilities after device is being added. Feature requires firmware version 5.70 or higher. Following settings of those devices are retrieved: - Currently configured streams
- Number of:
  - Video inputs
  - Streams per video input
  - Alarm inputs
  - Relays
  - Serial ports
- AutoDome 7000 series support
- Full support of VRM Pooling
- Server and Client SDK of Bosch VMS do not request recompilation of 3rd party integration when Bosch VMS 4.01 is upgraded to Bosch VMS 4.5.5 or later versions released in the future. Bosch VMS SDK of version 4.5.5 must be installed on the workstation running the SDK application using the new Setup option provided by Bosch VMS Setup.
- Web Client now supports IE 9 64bit and IE 10 64bit.

# 16 Bosch Video Management System Version 4.5.1

## 16.1 Feature enhancements in version 4.5.1

"Automatic Device Configuration" is now turned off by default and cannot be turned on anymore. Device Check is still checking the devices periodically. But mismatch errors and configuration of devices is only performed on activation.

# 17 Bosch Video Management System Version 4.5

## 17.1 New features in version 4.5

- Server Lookup
- Time zones
- VideoTec DCZ Keyboard support
- DVR 400/600/700 support
- Transcoding for low bandwidth transmission
- Export and import of configurations
- Enable TCP for live view
- Configuration Wizard
- Remote Access for Operator clients to Management Servers
- Web Client for live and playback video
- Storage state event
- Mobile Video Service (MVS) support of ONVIF, DVR, BRS

# 18 Bosch Video Management System Version 4.0

## 18.1 New features in version 4.0

- Enterprise System: Support of up to 10 subsystems
- Support of ONVIF compliant cameras
- Mobile Video Service
- Monitor Wall
- Bookmarks for Live and Playback mode
- Automatic map display
- RemoteClient Enterprise SDK
- Video Streaming Gateway available on Setup DVD.
- Cameo SDK 1.0 available on Setup DVD.
- Remote Logbook

# 19 Bosch Video Management System Version 3.0.1

## 19.1 New features in version 3.0.1

- Support for VIP X1 XF E
- Support for AutoDome 700 IP
- Support for Bosch Recording Station Appliance

# 20 Bosch Video Management System Version 3.0

## 20.1 New features in version 3.0

- Larger Systems with up to 2000 cameras, 100 workstations, and 40 VRMs
- Increased Reliability at multiple levels
  - Continuous Operation during Central Server maintenance, disconnection or downtime
  - High Availability Central Server with VMware
  - IP cameras and encoders can now record motion-based alarms independently of Central Server
  - Playback of video now possible when VRM not available
- Independent Operator Client
  - Continuous operation for live, playback and export during Central Server downtimes or while connection to Central Server not available
  - Any user can log on to an Operator Client not connected to Central Server
  - Automatic replenishment of user events to central logbook once connection to Central Server established again
- Latest IT environment
  - Windows Server 2008R2 64-bit support
  - Windows 7 64-bit SP1 support
- Better Operator Client performance by using up to 4GB RAM
- VIPXD-HD support with Single and Quad layout
- Dinion 1080p
- FlexiDome 1080p
- Improved debouncing with priorities
- Simplified and faster configuration of recording settings. Configure the settings per camera groups along your real-life project, not by technical differences of various camera types.
- New Default Qualities for easier configuration for 720p and 1080p with 5MBit/s target bit-rate and 10MBit/s max-bit rate
- Device Tree now displays the number of subnodes. When filtering is used the number of filtered and total is displayed
- Configuration Client now offers filtering for devices to allow easier configuration in large systems
- OSD on Alarm for VIPXD and VIPXD-HD is now also supported in Quad-Mode