

1.0 Product Version 1.12

1.1 New Feature

Support for Scancom 481, 581, 681.

1.2 Fixed Items

- The C900V2/C900TTL-E no longer sends repeated messages that are contained in a single IP packet.
- The duration of the simulated Dial-Tone is increased to support additional control panels.
- Random reset of an on-board relay is corrected.
- Communicators that use SIA Bell 103 now operate correctly when they send invalid messages.

