

From		Telephone	Nuremberg
STVC/PRM	Product Management	+49 911 93456 0	25.08.2008

## Release Letter

Product:	<b><i>MPEG-ActiveX</i></b>
Version:	<b><i>4.27.01.01</i></b>

This letter contains latest information about the above mentioned software version.

MPEG-ActiveX 4.27.01.01 is a maintenance release based on version 4.27.00.06 which was initially released together with BVIP firmware 3.52, Archive Player 2.22 and Configuration Manager 1.72.

This version supports enhanced Archive Player 2.22 functionalities.

### 1. Changes

- Wrong video image shown for a few seconds during playback from Video Recording Manager when going to last recording was fixed.
- A rare case of Unhandled Exception when taking snapshots in Archive Player 2.00 was fixed.
- A problem with VIDOS-NVR during reset was fixed.

From STVC/PRM	Product Management	Telephone +49 911 93456 0	Nuremberg 25.08.2008
------------------	--------------------	------------------------------	-------------------------

## 2. Restrictions; Known Issues

- For 32-bit color mode the PC must support YUV overlay.
- For MPEG-2 rendering on Nvidia graphic cards, use driver version 71.84 or older for optimal performance.
- Streaming works only if a RCP+ connection is established. If multicast streaming is enabled, a device can only connect to the stream if a RCP+ connection exists. Although the multicast address is enabled, the IP address must be set in addition.
- The following products are supported:  
VideoJet 10, VideoJet 8000, VideoJet 8008, VideoJet X series, VIP X1/X2/XD,  
VIP 10, VIP 1000, VIP X1600, Dinion IP, AutoDome IP, Flexidome IP,  
VIDOS-NVR, VIDOS Monitor Wall

•

## 3. System Requirements

- Desktop: Personal Computer
- CPU: Pentium IV, 1.8 GHz
- RAM: 256 MByte
- OS: Windows 2000/XP
- Graphic card: NVIDIA Quadro NVS 290 PCIe, NVIDIA Quadro FX 370 PCIe, ATI FireGL V5600 PCIe, NVIDIA Quadro FX 1700 PCIe, NVIDIA Quadro FX 3700 PCIe, or better
- Ethernet card: 100 MBit/s
- Sound card for audio
- Software: DirectX 9.0c