

## Adding H.264 devices to VIDOS v4.01

July 28, 2010

### Issue Severity:

- High: Act immediately
- Medium: Bosch Security Systems strongly recommends you take the action(s) described below.
- Low: Advisory

### Products Affected:

- Bosch H.264 devices, including:
  - NBC-455 Series
  - NDC-455 Series
  - NBN-498 Series
  - NDN-498 Series
  - VIDOS Video Management System 4.01

## 1.0 Issue

VIDOS v4.01 does not list the new Bosch H.264 BVIP devices. The Device tab in Configuration Manager, the Viewer, and the Archive Player lists these devices, but VIDOS Device tree does not list the H.264 devices.

The VIDOS v4.01 "devices.ini" file does not include the H.264 BVIP devices because these products were not available at the time of the VIDOS 4.1 release.

## 2.0 Resolution

Bosch has created a new "devices.ini" that includes the new H.264 BVIP devices. Download the new file from the Software tab on the VIDOS product page at [www.boschsecurity.com](http://www.boschsecurity.com). Then, copy the new file into this directory:

```
..\Program Files\Bosch\VIDOS\bin
```

Finally, restart VIDOS to load the H.264 devices into the Device tree.

Bosch plans to support all new Bosch H.264 devices part of the VIDOS v4.02 maintenance release planned for release in August, 2010.