

Security Systems <b>BOSCH</b>	<b>Software Release Notes</b> <b>CTFID 3.16</b>	Version: 02.00
----------------------------------	--	----------------

# Software Release Notes

## 1. Introduction

### 1.1 Disclaimer of Warranty

Bosch Security Systems, Inc. makes no representations or warranties, either expressed or implied, by or with respect to anything in this document, and shall not be liable for any implied warranties of merchantability or fitness for a particular purpose or for any indirect, special or consequential damages.

### 1.2 Purpose

The purpose of the *Software Release Notes* is to document is to communicate major new features and changes in this release of the Configuration Tool for Imaging Devices. It also documents component compatibility, workarounds, and any feature restrictions.

## 2. Support for New Products

CTFID version 3.16 adds support for the following cameras:

- **DINION 4000 AN**
  - VBN-4075-C11
  - VBN-4075-C21
  - VBN-4075-C51
  - VBC-4075-C11
  - VBC-4075-C21
  - VBC-4075-C51
- **DINION 5000 AN**
  - VBN-5085-C11
  - VBN-5085-C21
  - VBN-5085-C51
- **FLEXIDOME 5000 AN**
  - VDN-5085-V311
  - VDN-5085-V321
  - VDN-5085-VA11
  - VDN-5085-VA21
  - VDN-5085-V911
  - VDN-5085-V921
  - VDN-5085-V311S
  - VDN-5085-V321S
  - VDN-5085-VA11S
  - VDN-5085-VA21S
  - VDN-5085-V911S
  - VDN-5085-V921S
- **FLEXIDOME corner 9000 IR (VCN-9095 series)**

This release also includes defect fixes to support the MIC Series 612 and the AutoDome Easy II analog cameras.

Release Notes 01.00		Last Checked-In:	2012-Jan-19
© Robert Bosch GmbH reserves all rights even in the event of industrial property rights. We reserve all rights of disposal such as copying and passing on to third parties.			

<b>BOSCH</b>		Version: 02.00
	<b>Software Release Notes</b> CTFID 3.16	Date: 16 Jul 2013
		Page: 2 of 2

### 3. Software Changes

The following **ENHANCEMENTS** have been resolved for this delivery.

Description
Added support for FLEXIDOME corner 9000 MP
Added support for DINION 5000 AN and FLEXIDOME 5000 AN cameras.
Added translations for Thermal Spot Alarm features.

The following **DEFECTS** have been resolved for this delivery.

Description
Corrected mismatch between on-screen and log file humidity event counter.
Corrected issue where CTFID does not download a configuration for a device after a download occurred for a device previously connected.
Corrected issue where CTFID freezes if a user attempts to upload a migration file a device of a type other than the device currently connected.
Removed "Manual" as a White Balance option for AutoDome Easy II analog cameras.

### 4. Feature Restrictions

None.